					Bridge Inspection												
Bridge File Number 81038 SE-9 Bridge								Form Type			PSR						
Year Built/Year 2011/2011 Supstr							Lot	Lot No.			3						
Bridge or Town Name ANTHONY HENDAY(HWY 216)				SOLI	TU		Inspector Name			Wade Nanninga							
EAST RAMP OVER STONEY				NEY P	LAIN	RD		Inspector Class			BR CLS A						
Located Over 100 AVE (LOCAL ROAD))				Assistant Name									
Located On RAMP 4613-2 B								Assistant Class									
Water Body Cl./Year								Inspection Date			24-Jan-2013						
Navigabil. Cl./Year								Data Entry By				Theresa Lacusta					
Legal Land Location NW SEC 32 TWP 52 RGE 2				E 25 W	/4M		Dat				15-Feb-2013						
Longitude, Latitude -113:39:48, 53:				:32:	:28				Re	Reviewer Name				Eric Carcoux			
Road Authority Alberta Tr			rta Transp	orta	ation (A	IT)			-	Review Date				27-Jan-2013			
Contract Main. A	rea	ANT	HONY HE	ND	AY DR	IVE			De	pt. Rev	iewer	Name	Brent Herric	<			
Clear Roadway/	Skew	9.2 /								pt. Rev		ate	27-Feb-2013	27-Feb-2013			
AADT/Year		20,00	00 / 2013	(E)					Fol	low-Up	Ву						
Road Classificat	ion	RCU-	-209-110														
Detour Length (F	(m)																
Allowable Load ((t): Sing	gle (CS1 28			Sem	i C	S2 49			Traii	n CS	S3 62		> On Critic	al Spans	
															>Critical M		
Design Loading:		(CL800												> Primary S	3pan	
		_					P	osting	Infor	mation							
Required Vert. C					.,												
Posted Vertical (, ,	Yes	l		0.40.0	Ī.,							0.400	
Posted: Lane	WB	O	n Bridge ((m)	5.5	In Adv	ance	(Y/N)	Yes	Lane	e EB	S (C	On Bridge (m)		In Advance	(Y/N)	
Remarks		(1)			<u>.</u>												
Required Load F		(t)		Single						Semi			Truck Train				
Posted Loading			_	Single						Semi			Truck Train				
Posted:	Lane	SI			At Junction (Y/N)			No				(Y/N)	No		At Bridge (Y/N) No		
Posted:	Lane	N	В		At Junction (Y/N)					In Adv	/ance	(Y/N)		At Br	ridge (Y/N)		
Remarks																	
Hazard Marker A	At Bridg	je (Y/l	N) No														
Remarks																	
Other Sign Type	S		Max	60	Utilities (
Little Attackment							Ut	illities	(Loca	ited at)							
Utility Attachmer	าเร								0-			1					
Telephone	0	50	10/						Ga			04	4 15 1- 4				
Power	3 wire	SUM	VV							nicipal	\/ /N I\		Street lights				
Others									Pro	blem (Y/IN)	No					
Remarks								Appro	ooh E	Pood							
							Last				on of	Cond	ition				
Horizontal Aligni	ment						Last	6		Explanation of Condition Middle of horiz. curve.							
Vertical Alignme								8		Typical grade separation							
Roadway Width (m) 9.000		00															
Approach Bump	` ,		0.00					7									
Guardrail (Y/N) Yes																	
Guardrail (1714)				7		4m @											
Length (m) 11.400					45.	6m @	NVV/N	ΙΕ									
Current Standard (Y/N) Yes																	
Termination Ty	•	.,	FLE														
Drainage								7									
Approach Road	l Genei	ral Ra	ating					6									
		pproach Road General Rating							1								

			•	Superstructure								
Bridge Component					Explanation of Condition							
(Primary Span : NU, 1 Spans, Le	ngths(r	n): 39.127, A-	Ident N	lumber	:)							
Special Features												
(Primary Span: NU, 1 Spans, Lengths(m): 39.127, A				X								
				1								
				X								
			1									
)	2 (%)	3 (%)									
				1								
				8								
	l											
	No											
Deck Top				N								
Deck Rideability				8								
Deck Joints				4								
Temperature (deg. C)	-7				Missing curb coverplates @ NE/SWphoto							
	ABO-MA	UER, TRANS	FLEX,	ETC))	INISSING CUID COVERPLACES & INE/SVVPHOLO							
				• • • • • • • • • • • • • • • • • • • •								
	N abu	t										
80	S abu	t										
Deck Drainage				8								
Drains Clogged (Y/N)	No											
Curbs/Median				8								
(Curb Type : SINGLE SLOPE (CONCRI	ETE BARRIE	₹)									
Scaling (Percent Area)												
Bridge Rail				Х								
(Type:)												
Bridge Rail Posts				Х								
(Type:)												
Bridge Rail/Posts Coating				Х								
(Type:)												
Sidewalk				Х								
Girder Detail Ratings												
N (count) 1 (co	unt)	2 (count)	3 (cou	ınt)								
Last												
Now												
Girders				8	No visible NU typical cracks.							
Cracking (Y/N)	No											
Spalling (Percent Area)												
(Number Of Girders : 4)												
Diaphragms/Cross Frame				9								

Superstructure							
Bridge Component		Last	Now	Explanation of Condition			
(Primary Span : NU, 1 Spans, Le	ngths(m): 39.127, A-I	dent N	lumber	:)			
Bearings			8	Viewed from opposite embankment with binoculars.			
Temperature (deg. C)	-7						
(Expansion Type : REINFORCI TEFLON AND STAINLESS ST	ED NEOPRENE BEAR EEL)	RING W	/ITH				
(Fixed Type :)							
Coating Adequate (Y/N)	Yes						
Functioning (Y/N)	Yes						
Deck Underside			8				
Stains (Percent Area)							
Span Alignment Problems							
Vertical (Y/N)	No						
Horizontal (Y/N)	No						
Superstructure General Rating			8				
			Subst	ructure			
Bridge Component		Last	Now	Explanation of Condition			
Abutments							
Bearing Seats/Caps			9				
(Type : CONCRETE)							
Backwalls/Breastwalls			9				
Wingwalls			9				
Piles			N				
Paint/Coating			9				
Abutment Stability			8				
Scour/Erosion			8				
Piers/Bents							
(Type:)							
Bearing Seats/Caps			X				
(Type:)							
(Total Number of Bearing Piles :)							
Pier Shaft/Piles			X				
Bracing/Struts/Sheathing			Х				
Nose Plate			X				
Paint/Coating			X				
(Colour Description :)							
(Colour Code :)							
Pier Stability			X				
Scour			X				
Debris (Y/N)	No						
Substructure General Rating			8				

		S	re Usage					
		Last	Now	Explanation of Condition				
Grade Separation								
Road Alignment			9					
Traffic Safety Features			8					
Туре	Type Lights							
Slope Protection			4	S abut drop plate twisted upwardsphoto				
(Type : CONCRETE; CONCRE	TE)							
Bank Stability			8					
Drainage			8					
Grade Separation General Ratio	ng		4					

Bridge Inspection & Maintenance System (Web 2005)

		Maintenance Reco	ommend	ations					
Inspector Recommendations	Year	Inspector Comments		Department Com	nments		Target Year	Est. Cost	Cat #
REPAIR/REPLACE BRIDGE RAIL									
GALVANIZE/PAINT BRIDGE RAIL									
SEAL CURBS									
PATCH DECK									
SEAL DECK									
OVERLAY DECK									
REPAIR/REPLACE DECK JOINTS	2013	Install missing curb coverplate.(2)							
RESET/ PAINT BEARINGS									
WASHING									
SHOTCRETE REPAIRS									
REPAIR ABUTMENT SCOUR/EROSIG	ON								
PLACE ADDITIONAL RIP RAP									
REMOVE DRIFT ACCUMULATION									
OTHER ACTION	2013	Bend drip plate down @ S abut.							
OTHER ACTION									
OTHER ACTION									
OTHER ACTION									
OTHER ACTION									
Structural Condition Rating (Last/No. (%)	ow) /88.9	Sufficiency Rating (Last/No (%)	w) /	64.7	Est. Repl. Yr	2085	Maint. Re	qd. (Y/N)	Yes
Special Comments for Next Inspection	'	,		Department Comments			,		
Maintenance Reviewed By				Date			Estimated Total	0	
Proposed Long-Term Strategy									
On 3-Year Program (Y/N)									
Proposed Action									
Previous Inspector's Name		F	revious A	Assistant's Name					
Next Inspection Date	24-Oct-2014	P	revious I	nspection Date					
Inspection Cycle (Default) (months)	21								
Comment									