

Bridge Culvert Inspection			
Bridge File Number	81169 -1 Bridge Culvert	Form Type	CUL1
Year Built	1989	Lot No.	4
Bridge or Town Name	RED EARTH CR	Inspector Name	Brian Pientsch
Located Over	REDEARTH CREEK, 8.10.18.12.11, WATERCRS-ST	Inspector Class	BR CLS A
Located On	686:08 C1 4.059	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	10-Jan-2013
Legal Land Location	SW SEC 29 TWP 87 RGE 8 W5M	Data Entry By	Theresa Lacusta
Longitude, Latitude	-115:14:18, 56:34:11	Data Entry Date	02-Feb-2013
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Eric Carcoux
Contract Main. Area	CMA02	Review Date	23-Jan-2013
Clear Roadway/Skew	13.2 /	Dept. Reviewer Name	David Morrison
AADT/Year	460 / 2011 (A)	Dept. Review Date	21-Mar-2013
Road Classification	RCU-209G-90	Follow-Up By	
Detour Length (km)	300		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	4920	SP	40.8	152X51	3.0	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone		Gas	
Power		Municipal	
Others		Problem (Y/N)	No
Remarks	Sign "CP D261" South shoulder		

Approach Road / Embankment

	Last	Now	Explanation of Condition
Horizontal Alignment	8	8	
Vertical Alignment	9	9	
Roadway Width (m)	13.200		
Embankment	N	N	Snow covered
Sideslope (__:1)	4.5		
(Height of Cover(m) :)			
Guardrail (Y/N)	No		
Approach Road / Embankment General Rating	8	8	

Upstream End

Culvert Component	Last	Now	Explanation of Condition
Direction	S		
End Treatment (Concrete, Steel, Others, None)	CONCRETE		
Headwall	8	8	
Collar	N	N	Snowcovered.
Wingwalls	X	X	
(Shape :)			
Cutoff Wall	N	N	Snow covered.

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		N	N	Snow covered.
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		N	N	No evident problems.
(Type :)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		N	N	
Beavers (Y/N)	No			
Upstream End General Rating		7	7	(GR carried forward)
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 4920, Type: SP)				
Barrel Last Accessible Date	10-Jan-2013			Ice to crown 2.4m shape appears good.
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		7	7	No rise or span measurements due to ice above midpoint.
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)	200			Est. - ice.
Percent Sag	4			
Sidewall		7	7	Rated above ice.
Measured Span (mm)	5128			
Measured At Ring No.	5			
Deflection (mm)	208			
Percent Deflection	4			
Floor		N	N	Approx. 2.6m ice.
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		7	7	Rated above ice.
Separation (mm)				
Longitudinal Seams		7	7	Rated above ice.
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams				1N Stagger
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	Yes			
Coating		7	7	Rated above ice.
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)				
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	Yes			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 4920, Type: SP)				
Fish Passage Adequacy		7	7	
Baffle		X	X	
(Type :)				
Waterway Adequacy		7	7	No silt visible through ice.
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		7	7	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		(North)
End Treatment (Concrete, Steel, Others, None)		CONCRETE		
Headwall		7	7	
Collar		N	N	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		N	N	
Bevel End		N	N	Snow covered.
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		N	N	
(Type :)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		N	N	
Beavers (Y/N)		No		
Downstream End General Rating		7	7	GR carried forward.
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		5	5	
Bank Stability		5	5	
HWM (m below Top of Culvert)				NO HWM VISIBLE
Drift (Y/N)		No		
Channel Bottom Degrading/Aggrading				Dam 5m u/s.
Beavers (Y/N)		Yes		
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		5	5	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	77.8/77.8	Sufficiency Rating (Last/Now) (%)	74.0/73.8	Est. Repl. Yr	2039	Maint. Req'd. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Brian Pientsch		Previous Assistant's Name	Jordan Evans			
Next Inspection Date	10-Apr-2016		Previous Inspection Date	02-Feb-2009			
Inspection Cycle (Default) (months)	39						
Comment							