

Bridge Culvert Inspection			
Bridge File Number	81673 -1 Bridge Culvert	Form Type	CUL1
Year Built	1996	Lot No.	4
Bridge or Town Name	VULCAN	Inspector Name	Jason Rusu
Located Over	TRIBUTARY TO SNAKE CREEK, 12.2.4, WATERCRS-ST	Inspector Class	BR CLS B
Located On	534:02 C1 23.279	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	06-Mar-2010
Legal Land Location	SW SEC 1 TWP 17 RGE 24 W4M	Data Entry By	Kelsey Roberts
Longitude, Latitude	-113:10:48, 50:23:51	Data Entry Date	25-Mar-2010
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Garry Roberts
Contract Main. Area	CMA25	Review Date	12-Mar-2010
Clear Roadway/Skew	12 / -25 deg. (LHF)	Dept. Reviewer Name	Lorenz Bohnert
AADT/Year	760 / 2008 (A)	Dept. Review Date	26-Mar-2010
Road Classification	RLU-209G-90	Follow-Up By	
Detour Length (km)	6		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	2200	MP	44			ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments							
Telephone	South ditch	Gas					
Power	1 wire-north	Municipal					
Others			Problem (Y/N)	No			
Remarks							

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		9	8	
Vertical Alignment		8	8	
Roadway Width (m)	9.000			
Embankment		8	8	
Sideslope (__:1)	3.0			
(Height of Cover (m) : 3.3)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		8	8	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction		S		south
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	500			
Scour Protection		7	N	Snow covered
(Type : RIP RAP)				
(Avg. Rock Size (mm) : 250)				
Scour/Erosion		7	N	
Beavers (Y/N)	No			
Upstream End General Rating		7	N	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): -, Rise (mm): 2200, Type: MP)				
Barrel Last Accessible Date	06-Mar-2010			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		8	8	estimated sag of 1% not measured. shape is good.
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)	0			
Percent Sag				
Sidewall		8	8	Section #3 from U/S.
Measured Span (mm)	2180			
Measured At Ring No.	3			
Deflection (mm)	20			
Percent Deflection	1			
Floor		N	N	700mm of silt.
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		8	8	
Separation (mm)	30			
Longitudinal Seams		X	X	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)	0			
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		7	7	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): -, Rise (mm): 2200, Type: MP)				
Fish Passage Adequacy		8	8	
Baffle		X	X	
(Type :)				
Waterway Adequacy		8	8	Silting but not causing ponding.
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		8	8	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	50			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	500			
Scour Protection		7	N	Snow covered
(Type : RIP RAP)				
(Avg. Rock Size (mm) : 250)				
Scour/Erosion		7	N	
Beavers (Y/N)	No			
Downstream End General Rating		7	N	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	6	Channel enters u/s apron @ 45 deg
Bank Stability		8	8	
HWM (m below Top of Culvert)	0.5			
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	DEGRADING			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	6	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	88.9/88.9	Sufficiency Rating (Last/Now) (%)	84.8/80.0	Est. Repl. Yr	2043	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Tim Davies		Previous Assistant's Name				
Next Inspection Date	06-Jun-2013		Previous Inspection Date	26-Feb-2007			
Inspection Cycle (Default) (months)	39						
Comment							