

Bridge Culvert Inspection				
Bridge File Number	81677 -1 Bridge Culvert		Form Type	CUL1
Year Built	1999		Lot No.	4
Bridge or Town Name	NANTON		Inspector Name	Garry Roberts
Located Over	TRAIL-ANIMAL, OVER SP		Inspector Class	BR CLS A
Located On	533:02 C1 2.237		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	16-May-2010
Legal Land Location	NW SEC 25 TWP 14 RGE 2 W5M		Data Entry By	Erin Roberts
Longitude, Latitude	-114:09:04, 50:12:12		Data Entry Date	15-Jul-2010
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Tom Carey
Contract Main. Area	CMA27		Review Date	02-Jun-2010
Clear Roadway/Skew	12 /		Dept. Reviewer Name	Lorenz Bohnert
AADT/Year	1,040 / 2009 (A)		Dept. Review Date	23-Jul-2010
Road Classification	RAU-209-110		Follow-Up By	
Detour Length (km)				

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	2200	MP	32	125X26	2.8	ROUND
Special Features								
Special Features Comment								

Posting Information									
Required Vert. Clearance Posting (m)									
Posted Vertical Clearance (Y/N)									
Posted:	Lane	NB	On Bridge (m)	In Advance (Y/N)	Lane	SB	On Bridge (m)	In Advance (Y/N)	
Remarks	Not required								

Utilities (Located at)			
Utility Attachments			
Telephone	North SIDE		Gas
Power	SOUTH SIDE 100 m 1 LINE		Municipal
Others	Fibre optic - south side		Problem (Y/N) No
Remarks			

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		8	7	Short sight distance to the east
Vertical Alignment		5	5	
Roadway Width (m)	9.000			
Embankment		8	7	
Sideslope (___:1)	3.0			
(Height of Cover(m) : 1.7)				
Guardrail (Y/N)	Yes			
Approach Road / Embankment General Rating		5	5	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		NORTH END
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		8	8	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	400			
Scour Protection		X	7	
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		X	7	
Beavers (Y/N)	No			
Upstream End General Rating		8	7	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2200, Type: MP)				
Barrel Last Accessible Date	16-May-2010			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		8	8	est
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)	0			
Percent Sag				
Sidewall		8	8	INWARD
Measured Span (mm)	2174			
Measured At Ring No.	2			
Deflection (mm)	26			
Percent Deflection	1			
Floor		N	N	400mm of gravel
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		8	8	
Separation (mm)	10			
Longitudinal Seams		X	X	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)	0			
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		8	7	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2200, Type: MP)				
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type :)				
Waterway Adequacy		X	X	
Icing (Y/N)	No			
Siltng (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		8	8	

Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		SOUTH END
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		8	8	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	400			
Scour Protection		X	7	
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		X	7	
Beavers (Y/N)	No			
Downstream End General Rating		8	7	

Structure Usage				
		Last	Now	Explanation of Condition
Grade Separation				
Road Alignment		7	X	
Roadway Surface		7	7	
(Type :)				
Icing (Y/N)	No			
Traffic Safety Features		X	X	
Type				
Lighting		X	X	
Barrel Leakage (Y/N)	No			

Structure Usage				
		Last	Now	Explanation of Condition
Drainage		7	7	
Structure In Use (Y/N)	No			Fenced off
Grade Separation General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	88.9/88.9	Sufficiency Rating (Last/Now) (%)	90.3/88.0	Est. Repl. Yr	2048	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Tim Davies		Previous Assistant's Name				
Next Inspection Date	16-Aug-2013		Previous Inspection Date	16-Jan-2007			
Inspection Cycle (Default) (months)	39						
Comment							