				Bri	idae	- Culve	ert Inspe	ection						
Bridge File Nur	mber	81847 -1 Bridge Culvert						Form Type		CUL1				
Year Built	11501	1991				Lot				4				
Bridge or Town Name WAINWRIGHT							Inspector Name		Jason Saly					
Located Over TRAIL-ANIMAL, OVER SP				R SP			Inspector Class		BR CLS A					
Located On 883:02 C1 19.601				01			Assistant Name		DIX OLO /X					
Water Body Cl./Year								nt Class						
Navigabil. Cl./Year								Inspection Date		27-Nov-2012				
Legal Land Location NW SEC 30 TWP 46 RGE 6 W4M							Data Entry By			Marcia Chavez	7			
Longitude, Latitude -110:52:05, 52:59:56							Data Entry Date		17-Jan-2013					
Road Authority Alberta Transportation (AIT)							Reviewer Name			John O'Brien				
Contract Main. Area CMA15			i (Ai i)				Review Date		14-Dec-2012					
Clear Roadway/Skew 10.2 / 0 deg.					Dept. Reviewer Name									
						Dept. Reviewer Name Dept. Review Date		18-Jan-2013						
		RCU-20					· · · · · ·		alG	10-3411-2013				
Detour Length		8	9-110				Follow-Up By							
Bridge Culvert	,									<u> </u>				
Number of Culv			 1											
Pipe #	Barrel		span	Rise (or Dia	\	Туре		Length		Corr. Profile	Pl./Slab	Shape		
ripe #	Danei		эран	Kise (oi Dia	.,	Type		Lengui		Con. Frome	Thickness	Snape		
1	MAIN		-	2200	MP			36.2			2.8	ROUND		
Special Feature	es													
Special Feature	es Comr	ment												
					Pos	sting Ir	nformati	on						
Required Vert.														
Posted Vertical														
Posted: Lane			ridge (m)	In Advance	ce (`	Y/N) I	No La	ane SB	0	n Bridge (m)	In Advan	ce (Y/N) No		
Remarks	Not re	quired, c	attlepass.											
Little Attackers					<u>Util</u>	lities (L	ocated	at)						
Utility Attachme		Courth di	t o b				Coo		Aaraa	o o/l 10m \\/oot	of nino			
Telephone	Along	South di	ich.				Gas		ACIOS	cross c/l 10m West of pipe.				
Power							Municip		No					
Others							Probler	11 (Y/IN)	No					
Remarks				Anne		h Door	d / Embe	ankment						
				Appr		Now		ation of		tion				
Horizontal Aligr	nment				31 7	7	<u> </u>	Rge Road 6-5A, 140m E of pipe. Crest W of pipe; no passing						
Vertical Alignm					, 6	6	limited	sight dist	ance to	o W.	t vv or pipe, no	passing VVD,		
			10.200											
Roadway Width (m) 10.200														
Embankment					8	N	Snow o	Snow covered.						
Sideslope (:1)													
	,		3.0											
(Height of Co		3.2)	3.0				1							
(Height of Co Guardrail (Y/N)	ver(m):	3.2)	No											
	ver(m):	3.2)				ı								
	ver(m) :		No	ting	6	6								
Guardrail (Y/N)	ver(m) :		No	ting			am End							
Guardrail (Y/N) Approach Roa	over(m) :		No	, 3		Upstre	am End		Condi	tion				
Guardrail (Y/N) Approach Roa Culvert Compo	over(m) :		No	La				ation of	Condi	tion				
Guardrail (Y/N) Approach Roa Culvert Compo	over(m) :	oankmen	No at General Ra	, 3		Upstre			Condi	tion				
Guardrail (Y/N) Approach Roa Culvert Compo	over(m) :	oankmen	No at General Ra	La		Upstre			Condi	tion				
Guardrail (Y/N) Approach Roa Culvert Componication End Treatment	over(m) :	oankmen	No at General Ra	La N		Upstre			Condi	tion				

			Heetus	om End
Culvert Component		Last	Now	am End Explanation of Condition
Wingwalls		X	X	Explanation of Condition
(Shape:)				
Cutoff Wall		X	V	
Cuton wan		^	X	
Bevel End		X	X	Projects from fill 2.5m.
Heaving (mm)	0			Squared end.
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection		X	N	Snow covered.
(Type:)				
(Avg. Rock Size(mm):)				
Scour/Erosion		X	X	
Beavers (Y/N)	No			
Upstream End General Rating		7	7	
		Del	dae Cu	lvert Barrel
Culvert Component			Now	Explanation of Condition
(Pipe # : 1, Primary Span, Loca	tion Code: MAIN S			, Rise (mm): 2200, Type: MP)
Barrel Last Accessible Date	27-Nov-2012	Pari (IIIII	.,.	, ()
Dairei Last Accessible Date	27-1100-2012			
Special Features				
Special Feature				
(Type:)				
Special Feature				
(Type:)				
Roof		6	6	
Measured Rise (mm)	2090			
Measured At Ring No.	3			
Sag (mm)	110			Estimated.
Percent Sag	5			
Sidewall		6	6	Span at S end=2200=omm
Measured Span (mm)	2308			Span at mid=2308=108mm=4.9% Span at N end=2186=14mm
Measured At Ring No.				
Deflection (mm)	108			4.9%
Percent Deflection	5			
Floor		N	N	Gravel covered.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	7	
Separation (mm)	35			
Longitudinal Seams		Х	Х	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		7	6	
Corrosion By Soil (Y/N)	No			

		Brio	dge Cu	lvert Barrel
Culvert Component		Last	Now	Explanation of Condition
(Pipe #: 1, Primary Span, Loca	tion Code: MAIN, Spa	n (mm	n):	, Rise (mm): 2200, Type: MP)
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	Х	
(Type:)				
Waterway Adequacy		Х	X	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		6	6	
				eam End
Culvert Component			Now	Explanation of Condition
Direction		S		
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		Х	X	
Collar		X	X	
Wingwalls		X	X	
(Shape:)				
Cutoff Wall		Х	X	
Bevel End		Х	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection		X	N	Snow covered.
(Type:)				
(Avg. Rock Size(mm):)				
Scour/Erosion		Х	X	
Beavers (Y/N)	No			
Downstream End General Ratio	ng	7	7	
				re Usage
		Last	Now	Explanation of Condition
Grade Separation			1	
Road Alignment		9	9	
Roadway Surface		8	8	
(Type : GRAVEL)				
Icing (Y/N)	No			
Traffic Safety Features		X	X	
Туре	None			
Lighting		X	X	
Barrel Leakage (Y/N)	No			

Structure Usage										
		Last	Now	Explanation of Condition						
Drainage		8	8							
Structure In Use (Y/N)	Yes									
Grade Separation General Rating			8							

			Mainten	ance Recommer	dations					
nspector Recommendations Year Inspector Comments					Department Com	ments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS										
PLACE ADDITIONAL RIP RAP										
REMOVE DRIFT ACCUMULATION										
INSTALL CONCRETE/STEEL LINING	6									
INSTALL STRUTS										
INSTALL CONCRETE COLLAR/CUT	OFF									
REPAIR SEAMS										
OTHER ACTION										
OTHER ACTION										
OTHER ACTION										
OTHER ACTION										
Structural Condition Rating (Last/N (%)	ow) 66.7/	66.7/66.7 Sufficiency Rating (%)		g (Last/Now)	78.9/79.1	Est. Repl. Yr	2050	Maint. Re	qd. (Y/N)	No
Special Comments for Next Inspection					Department Comments					
Maintenance Reviewed By					Date		E	stimated Tota	I 0	
Proposed Long-Term Strategy										
On 3-Year Program (Y/N) Y										
Proposed Action	2007.12.29 (Check for saf	ety in respect to lac	kof guardrails.Bro	wnlee & Associates					
Previous Inspector's Name	Previous Inspector's Name Owen Salava Previous									
Next Inspection Date	27-Feb-2016	7-Feb-2016 Previous			s Inspection Date	27-Jan-2010				
Inspection Cycle (Default) (months)	39									
Comment										