

Bridge Culvert Inspection			
Bridge File Number	82282 -1 Bridge Culvert	Form Type	CUL1
Year Built	2003	Lot No.	1
Bridge or Town Name	GREENCOURT	Inspector Name	Kris Bosters
Located Over	TRIBUTARY TO LITTLE PADDLE RIVER, 8.11.84.30.19.12, WATERCRS-ST	Inspector Class	BR CLS A
Located On	LOCAL ROAD	Assistant Name	Brian Cote
Water Body Cl./Year		Assistant Class	BR CLS B
Navigabil. Cl./Year		Inspection Date	18-Apr-2013
Legal Land Location	SW SEC 31 TWP 58 RGE 9 W5M	Data Entry By	Lisa Fairhurst
Longitude, Latitude	-115:20:21, 54:03:15	Data Entry Date	24-Apr-2013
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Eric Carcoux
Contract Main. Area	UNDEFINED CMA	Review Date	21-Apr-2013
Clear Roadway/Skew	8 /	Dept. Reviewer Name	Brent Herrick
AADT/Year	5 / 2013 (E)	Dept. Review Date	01-May-2013
Road Classification	RLU-208G-90	Follow-Up By	
Detour Length (km)	999		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	2700	MP	36	125X26	2.8	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone		Gas	
Power		Municipal	
Others		Problem (Y/N)	No
Remarks	No BF tag installed.		

Approach Road / Embankment

	Last	Now	Explanation of Condition
Horizontal Alignment	7	7	"T" intersection, resident/field access only. Access via South service road off Hwy 43.
Vertical Alignment	9	9	
Roadway Width (m)	8.000		
Embankment	8	8	(Ditch erosion repaired with rock @ NW corner.- May 21/2008)
Sideslope (___:1)	4.0		
(Height of Cover(m) : 2)			
Guardrail (Y/N)	Yes		3 damaged sections, 1 broken post at NE corner
Approach Road / Embankment General Rating	7	7	

Upstream End

Culvert Component	Last	Now	Explanation of Condition
Direction	W		
End Treatment (Concrete, Steel, Others, None)	STEEL		
Headwall	X	X	
Collar	X	X	
Wingwalls	X	X	
(Shape :)			

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Cutoff Wall		X	X	
Bevel End		8	8	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	700			
Scour Protection		8	N	(Minor sluffing of sideslope upstream of the end of the rock riprap. - May 21/2008)
(Type : RIP RAP, GEOTEXTILE)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		8	N	
Beavers (Y/N)	No			Drift @ opening - photo.
Upstream End General Rating		8	8	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1 , Primary Span, Location Code: MAIN , Span (mm): , Rise (mm): 2700 , Type: MP)				
Barrel Last Accessible Date				Viewed from end. Shape & condition very good.
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		8	N	
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)				
Percent Sag				
Sidewall		N	N	Water 1.2m clear to crown.
Measured Span (mm)				
Measured At Ring No.				
Deflection (mm)				
Percent Deflection				
Floor		N	N	
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		N	N	
Separation (mm)				
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		8	N	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2700, Type: MP)				
Ponding (Y/N)	No			
Fish Passage Adequacy		8	8	
Baffle		N	N	
(Type : WEIR)				
Waterway Adequacy		8	8	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	Yes			
Barrel General Rating		N	N	Previous rating was "8".
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		8	8	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	700			
Scour Protection		8	N	Ice and snow covered. Deep fast moving water
(Type : RIP RAP, GEOTEXTILE)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		8	N	
Beavers (Y/N)	No			
Downstream End General Rating		8	8	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		8	8	
Bank Stability		6	5	Fast moving and down cutting stream
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	Yes			
Channel Bottom Degrading/Aggrading	DEGRADING			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		6	8	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION	2013	At U/S end (W).					
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2013	Dewater and Level II inspection					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	55.6/55.6	Sufficiency Rating (Last/Now) (%)	72.3/73.6	Est. Repl. Yr	2054	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Dave Lam		Previous Assistant's Name				
Next Inspection Date	18-Jan-2018		Previous Inspection Date	21-May-2008			
Inspection Cycle (Default) (months)	57						
Comment							