

Bridge Inspection										
Bridge File Number	83057 -1 Bridge				Form Type	TT				
Year Built/Year Supstr	1986/1986				Lot No.	4				
Bridge or Town Name	N COOKING LA				Inspector Name	Jason Saly				
Located Over	WATERCOURSE, WATERCRS-NI				Inspector Class	BR CLS A				
Located On	TRAIL-PED, ON 50000 FB				Assistant Name					
Water Body Cl./Year					Assistant Class					
Navigabil. Cl./Year					Inspection Date	28-Nov-2011				
Legal Land Location	NW SEC 18 TWP 52 RGE 20 W4M				Data Entry By	Marcia Chavez				
Longitude, Latitude	-112:57:05, 53:29:34				Data Entry Date	03-Jan-2012				
Road Authority	Alberta Transportation (AIT)				Reviewer Name	John O'Brien				
Contract Main. Area	UNDEFINED CMA				Review Date	15-Dec-2011				
Clear Roadway/Skew	3 /				Dept. Reviewer Name	Andrew Smikles				
AADT/Year					Dept. Review Date	09-Jan-2012				
Road Classification	RLU-207G-60				Follow-Up By					
Detour Length (km)										
Allowable Load (t):	Single		Semi		Train		----> On Critical Spans ---->Critical Member			
Design Loading:							----> Primary Span			

Posting Information										
Required Load Posting (t)	Single				Semi				Truck Train	
Posted Loading (t)	Single				Semi				Truck Train	
Posted:	Lane	EB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No		
Posted:	Lane	WB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No		
Remarks										
Hazard Marker At Bridge (Y/N)	No									
Remarks										
Other Sign Types										

Utilities (Located at)										
Utility Attachments										
Telephone					Gas					
Power					Municipal					
Others					Problem (Y/N)	No				
Remarks										

Approach Road									
			Last	Now	Explanation of Condition				
Horizontal Alignment			5	5	TRAILS				
Vertical Alignment			5	5					
Roadway Width (m)	3.700								
Approach Bump			5	N	Snow covered.				
Guardrail (Y/N)	No								
Guardrail			X	X					
Length (m)									
Current Standard (Y/N)	No								
Termination Type	None								
Drainage			5	N	Snow covered.				
<b>Approach Road General Rating</b>			<b>5</b>	<b>5</b>					

Superstructure						
Bridge Component		Last	Now	Explanation of Condition		
(Primary Span : <b>TT</b> , <b>1 Spans</b> , <b>Lengths(m): 5.5</b> , <b>A-Ident Number:</b> )						
<b>Special Features</b>						
Special Feature			X			
(Type : )						
Special Feature			X			
(Type : )						
Wearing Surface/Deck Top Detail Ratings						
	N (%)	1 (%)	2 (%)	3 (%)		
<b>Last</b>						
<b>Now</b>	100.0	0.0	0.0	0.0		
Wearing Surface/Deck Top				5	N	Snow covered.
(Material Type : <b>TREATED TIMBER</b> )						
(Plank Thickness(mm) : <b>75</b> )						
(Plank Width(mm) : <b>300</b> )						
Deck Rideability				5	7	
Wheel Guards				5	N	Snow covered.
(Curb Type : <b>Standard</b> )						
(Type : <b>TREATED TIMBER</b> )						
(Thickness(mm) : <b>150</b> )						
(Width(mm) : <b>150</b> )						
Bridge Rail				5	Approx. 1.0m to streambed. Rail 100x50mm.	
(Type : <b>TREATED TIMBER BRIDGE SOLID BEAM (EX. TIMBER RAILS)</b> )						
Bridge Rail Posts		X		6	Posts 100x100mm.	
(Type : <b>TREATED TIMBER;TREATED TIMBER</b> )						
Bridge Rail/Posts Coating		X		X		
(Type : )						
(No. of Stringers : <b>7</b> )						
Stringer Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
<b>Last</b>						
<b>Now</b>	0	0	0	0		
Stringers				5	7	
(Type : <b>TREATED TIMBER</b> )						
(Width(mm) : <b>200</b> )						
(Depth(mm) : <b>310</b> )						
(Spacing(mm) : <b>660</b> )						
Sub Deck/Deck Underside				X	6	Underside of wearing surface (single layer of TT).
(Material Type : <b>TREATED TIMBER</b> )						
(Plank Thickness(mm) : <b>75</b> )						
(Plank Width(mm) : <b>300</b> )						
Defects (Percent Area)						
<b>Span Alignment Problems</b>						
Vertical (Y/N)		No				
Horizontal (Y/N)		No				
<b>Superstructure General Rating</b>				<b>5</b>	<b>7</b>	

Substructure						
Bridge Component				Last	Now	Explanation of Condition
<b>Abutments</b>						
(Extended Backwall Piles (Y/N) : )						
(Extended Backwall Piles Spacing(mm) : )						
(Total Number of Caps/Corbels : <b>1:1</b> )						
Bearing Seats/Caps/Corbels Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
<b>Last</b>						
<b>Now</b>	2	0	0	0		Dirt up to stringers.
Bearing Seats/Caps/Corbels				X	N	
(Type : <b>TREATED TIMBER</b> )						
(Depth(mm) : <b>200</b> )						
(Width(mm) : <b>500</b> )						
Backwalls/Breastwalls				X	X	
Greatest Height (m)						
Wingwalls				X	X	
(Total Number of Bearing Piles : <b>0:0</b> )						
Piles Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
<b>Last</b>						
<b>Now</b>	0	0	0	0		
Piles				X	X	
Paint/Coating				X	X	
Abutment Stability				5	7	
Scour/Erosion				5	7	
<b>Piers/Bents</b>						
(Type : )						
(Total Number of Caps/Corbels : )						
Bearing Seats/Caps/Corbels Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
<b>Last</b>						
<b>Now</b>						
Bearing Seats/Caps/Corbels				X	X	
(Type : )						
(Depth(mm) : )						
(Width(mm) : )						
(Total Number of Bearing Piles : )						
Piles Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
<b>Last</b>						
<b>Now</b>						
Pier Shaft/Piles				X	X	
Greatest Height (m)						
Bracing/Struts/Sheathing				X	X	
Nose Plate				X	X	
Paint/Coating				X	X	
(Colour Description : )						
(Colour Code : )						
Pier Stability				X	X	

Substructure				
Bridge Component		Last	Now	Explanation of Condition
Scour		X	X	
Debris (Y/N)	No			
<b>Substructure General Rating</b>		<b>5</b>	<b>7</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel</b>				
(U/S Direction : <b>N</b> )				
(D/S Direction : <b>S</b> )				
Alignment		6	6	
Bank Stability		6	6	
HWM (m below Top of Curb)				HWM not visible.
Drift (Y/N)	No			
Slope Protection		5	5	
(Type : <b>NATURAL; NATURAL</b> )				
Guidebank/Spurs		X	X	
Adequacy of Opening		5	5	
(Fish Compensation Measure 1 : <b>NONE</b> )				
(Fish Compensation Measure 2 : <b>NONE</b> )				
<b>Channel General Rating</b>		<b>5</b>	<b>5</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL							
PATCH DECK							
REPLACE STRIP DECK							
REPLACE SUB DECK							
STRAIGHTEN/REPLACE MEMBERS							
WASHING							
CORE TIMBER CAPS/CORBELS							
REPAIR/REPLACE TIMBER CAPS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL STRUTS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>55.0/77.8</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>51.2/85.3</b>	Est. Repl. Yr	2018	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Aime Theroux		Previous Assistant's Name				
Next Inspection Date	28-Aug-2016		Previous Inspection Date	12-Nov-2002			
Inspection Cycle (Default) (months)	57						
Comment							