					В	ridge Ir	nspectio	n					
Bridge File Number	83068 -1	Bridge				_ Ŭ				TT			
Year Built/Year	2002/200						Lot No.		4				
Supstr							Inspector Name			Jason Saly			
Bridge or Town Name	N COOK	ING LA				Inspector Class				BR CLS A			
Located Over	WATERO	COURSE	, WATEF	RCRS-N	l		Assistant Name						
Located On	TRAIL-P	ED, ON 5	0000 F	В			Assistant Class						
Water Body Cl./Year								ion Date		28-Nov-2011			
Navigabil. Cl./Year						Data Entry By				Marcia Chavez			
Legal Land Location	NE SEC	12 TWP	52 RGE	20 W4N	1	Data Entry Date			03-Jan-2012				
Longitude, Latitude	-112:48:2	21, 53:28:	:36				Reviewer Name			John O'Brien			
Road Authority	Alberta T	ransporta	ation (Al	T)			Review Date						
Contract Main. Area	UNDEFI	NED CMA	4							15-Dec-2011			
Clear Roadway/Skew	3 /									09-Jan-201	Andrew Smikles		
AADT/Year							· ·			09-Jan-201			
Road Classification	on RLU-207G-60						Follow-Up By						
Detour Length (km)													
Allowable Load (t): Sir	ngle Sem		Semi			Train		1	'	> On Critical Spans		ical Spans	
Design Loading:	esign Loading:		<u> </u>								> Primary		
					Ро	sting Ir	nformati	on				,	'
Required Load Posting	ı (t)		Single					Semi			Truck Train		
Posted Loading (t)			Single				Semi				Truc	k Train	
Posted: Lane	NB			tion (Y/N	1)	No	In A	Advance	(Y/N)	No	At Bı	ridge (Y/N)	No
Posted: Lane	SB			tion (Y/N		No		Advance	` ,	No	At Bridge (Y/N)		No
Remarks				•	, ,				, ,			<u> </u>	
Hazard Marker At Brid	ae (Y/N)	No											
Remarks	<b>J</b> · ( · )												
Other Sign Types													
o men engan nyaéta					Uti	lities (L	ocated	at)					
Utility Attachments													
Telephone							Gas						
Power								Municipal					
Others							Problem (Y/N) No		No				
Remarks							1 100101	11 (1714)	1110				
Romano						Annroa	ch Road	1					
				L	ast	Now		ation of	Condi	tion			
Horizontal Alignment					5	6	TRAILS; OK for designed use.						
Vertical Alignment					5	6	1	,	- 9.				
Roadway Width (m)		4.000					(3.95)						
Approach Bump					5	6	(====)						
Guardrail (Y/N)		No											
Guardrail		110			X	X							
Length (m)					•								
Current Standard (Y/	/N)	No											
Termination Type	14)	None											
Drainage		INOTIE			5	5							
Diamage					3	5							
Approach Road Gene	eral Ratin	g			5	6							

						structure
Bridge Comp					Now	Explanation of Condition
(Primary Spa	n : <b>TT, 1 Spar</b>	ns, Lengths(m	n): 5.5, A-Iden	t Num	ber: )	
Special Feat	ures					
Special Featu	ıre				X	
(Type:)						
Special Featu	ıre				X	
(Type:)						
Wearing Surf	ace/Deck Top	Detail Ratings	5			
	N (%)	1 (%)	2 (%)	3 (%)		
Last						Snow covered.
Now	100.0	0.0	0.0		0.0	
Wearing Surf	ace/Deck Top			5	N	
(Material Ty	/pe : <b>TREATE</b>	D TIMBER)				
(Plank Thic	kness(mm) : <b>7</b>	<b>75</b> )				
(Plank Widt	th(mm) : <b>300</b> )					
Deck Rideabi	ility			5	5	
Wheel Guard				5	6	
` .	: Standard)					
` • •	EATED TIMBE	ER)				
(Thickness)						
(Width(mm)	) : 150)					
Bridge Rail					6	DECK TO STREAMBED APPROX. 1.0m. Rail system is removable for easy repairs.
		BEAM (EX. TI	MBER RAILS	)) X		Rail 100x50mm.
Bridge Rail Posts					6	_
(Type : TREATED TIMBER;TREATED TIMBER)  Bridge Rail/Posts Coating					1	Posta 100x100mm.
Bridge Rail/Posts Coating					X	_
(Type:)						
(No. of String	ers : <b>7</b> )					
Stringer Deta	_					
	N (count)	1 (count)	2 (count)	3 (cou	unt)	
Last						
Now	0	0	0		0	_
Stringers				5	7	
	EATED TIMBE	ER)				
(Width(mm)	•					
(Depth(mm						
(Spacing(m					_	
	ck Underside			X	7	Deck underside of single layer of TT.
	/pe : <b>TREATE</b>					
	kness(mm): 7	<b>'</b> 5)				
	th(mm) : <b>300</b> )					
Defects (Pe	ercent Area)					
Span Alignm	ent Problems	s				
Vertical (Y/I	N)	No				
Horizontal (	(Y/N)	No			_	
Superstructu	ure General R	ating		5	7	
					Subst	ructure
Bridge Comp	oonent			Last	Now	Explanation of Condition
Abutments						
	Backwall Piles					
(Extended I	Backwall Piles	Spacing(mm)	:)			

						ructure
Bridge Comp	onent			Last	Now	Explanation of Condition
(Total Numbe	er of Caps/Cor	bels : 2:2)				Timber caps on mud sill.
Bearing Seats	s/Caps/Corbe	ls Detail Rating	gs			
	N (count)	1 (count)	2 (count)	3 (co	unt)	
Last						
Now	0	0	0		0	
Bearing Seats	s/Caps/Corbe	ls		5	7	
(Type : TRE	EATED TIMBI	ĒR)				
(Depth(mm)	) : <b>250</b> )					
(Width(mm)	: 250)					
	•			X	Х	
Greatest He	eight (m)					
Wingwalls	<u> </u>			Х	Х	
(Total Numbe	er of Bearing F	Piles : <b>0:0</b> )		<u> </u>		
Piles Detail R	atings					
	ast low 0 0 0  Bearing Seats/Caps/Corbels (Type : TREATED TIMBER) (Depth(mm) : 250) (Width(mm) : 250) Backwalls/Breastwalls Greatest Height (m) Vingwalls  Total Number of Bearing Piles : 0:0) Biles Detail Ratings N (count) 1 (count) 2 (count/Coast   Count/Coast   Coun				unt)	
Last						
Now	0	0	0		0	
Piles				Х	X	
				Х	Х	
Abutment Sta	bility			5	5	
Scour/Erosion	า			5	5	
		d1 \				
Bearing Seats	<u> </u>	1		0 /	4\	
Last	in (count)	1 (count)	2 (count)	3 (co	unt)	
	o/Cana/Carba	lo		X	X	-
	s/Caps/Corbe	15				
	· · · ·					
Bearing Seats/Caps/Corbels (Type: TREATED TIMBER) (Depth(mm): 250) (Width(mm): 250) Backwalls/Breastwalls Greatest Height (m) Wingwalls  (Total Number of Bearing Piles: 0:0) Piles Detail Ratings    N (count)						
		2:1				
		riles : )				
Piles Detail R		1 (aquat)	2 (20 unt)	3 (co	.m+\	
Loct	in (courit)	i (courit)	Z (Courit)	3 (60)	urit)	
				X	X	-
				X	X	
	5/Sileatiling					
Nose Plate				X	X	
Paint/Coating				X	X	
(Colour Des						
(Colour Cod	de : )					
Pier Stability				X	X	
Scour				Х	Х	

			Subst	structure				
Bridge Component		Last Now		Explanation of Condition				
Debris (Y/N)	Yes							
Substructure General Rating		5	5					
		5	Structu	re Usage				
		Last	Now	Explanation of Condition				
Channel								
(U/S Direction : )				Unknown.				
(D/S Direction:)								
Alignment		7	7					
Bank Stability		7	7					
HWM (m below Top of Curb)				HWM not visible.				
Drift (Y/N)	Yes							
Slope Protection		5	5	A little bit of rock under bridge.				
(Type: NATURAL; NATURAL	-)							
Guidebank/Spurs		X	X					
Adequacy of Opening	Adequacy of Opening		5					
(Fish Compensation Measure 1	: NONE)							
(Fish Compensation Measure 2	: NONE)							
Channel General Rating		5	5					

		Maintenance	Recommend	lations					
Inspector Recommendations	Year	Inspector Comments		Department Con	ments		Target Year	Est. Cost	Cat #
REPAIR/REPLACE BRIDGE RAIL									
PATCH DECK									
REPLACE STRIP DECK									
REPLACE SUB DECK									
STRAIGHTEN/REPLACE MEMBERS									
WASHING									
CORE TIMBER CAPS/CORBELS									
REPAIR/REPLACE TIMBER CAPS									
REPAIR ABUTMENT SCOUR/EROSI	ON								
PLACE ADDITIONAL RIP RAP									
REMOVE DRIFT ACCUMULATION									
INSTALL STRUTS									
OTHER ACTION									
OTHER ACTION									
OTHER ACTION									
OTHER ACTION									
Structural Condition Rating (Last/N (%)	ow) 55.0/66	.7 Sufficiency Rating (Las (%)	st/Now)	51.2/81.5	Est. Repl. Yr	2020	Maint. Red	qd. (Y/N)	No
Special Comments for Next Inspection				Department Comments					
Maintenance Reviewed By				Date			Estimated Total	0	
Proposed Long-Term Strategy									
2 2 4 4 8 8									
On 3-Year Program (Y/N)									
On 3-Year Program (Y/N) Proposed Action									
	Aime Theroux		Previous	Assistant's Name					
Proposed Action	Aime Theroux 28-Aug-2016			Assistant's Name	13-Nov-2002	2			
Proposed Action  Previous Inspector's Name					13-Nov-2002	2			