

Bridge Culvert Inspection			
Bridge File Number	08365 -1 Bridge Culvert	Form Type	CUL1
Year Built	1959	Lot No.	4
Bridge or Town Name	TABER	Inspector Name	Garry Roberts
Located Over	TRIBUTARY TO OLDMAN RIVER, 2.12.4, WATERCRS-ST	Inspector Class	BR CLS A
Located On	864:02 C1 20.291	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	19-Mar-2012
Legal Land Location	SW SEC 36 TWP 11 RGE 17 W4M	Data Entry By	Lauren Korte
Longitude, Latitude	-112:12:40, 49:57:04	Data Entry Date	12-Apr-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Tom Carey
Contract Main. Area	CMA24	Review Date	23-Mar-2012
Clear Roadway/Skew	9.7 / -10 deg. (LHF)	Dept. Reviewer Name	Tim Davies
AADT/Year	490 / 2011 (A)	Dept. Review Date	17-Apr-2012
Road Classification	RCU-209-110	Follow-Up By	
Detour Length (km)	6		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	1450	1600	SPE	74.4	152X51	2.8,2.8,2.8	ELLIPSE
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments				
Telephone	West side.	Gas		
Power	3 wires on East r/w.	Municipal		
Others		Problem (Y/N)	No	
Remarks				

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		9	9	
Vertical Alignment		7	7	
Roadway Width (m)	9.700			
Embankment		6	5	
Sideslope (__:1)	1.5			
(Height of Cover(m) : 7.6)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		7	7	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction		W		West invert.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		N	7	
Heaving (mm)	100			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		N	7	
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		N	7	
Beavers (Y/N)	No			
Upstream End General Rating		5	7	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1450, Rise (mm): 1600, Type: SPE)				
Barrel Last Accessible Date	19-Mar-2012			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		7	7	
Measured Rise (mm)	1540			
Measured At Ring No.	11			
Sag (mm)	60			
Percent Sag	3			
Sidewall		7	7	
Measured Span (mm)	1485			
Measured At Ring No.	11			
Deflection (mm)	14			
Percent Deflection	1			
Floor		7	7	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	7	
Separation (mm)	0			
Longitudinal Seams		7	7	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	Yes			1 N stagger.
Coating		7	6	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1450, Rise (mm): 1600, Type: SPE)				
Fish Passage Adequacy		X	7	
Baffle		X	X	
(Type :)				
Waterway Adequacy		8	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		7	7	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		East invert.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		N	6	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		N	5	
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		N	5	Shallow scour hole D/S.
Beavers (Y/N)	No			
Downstream End General Rating		4	5	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	7	Berms U/S and D/S to create ponds for livestock.
Bank Stability		7	7	
HWM (m below Top of Culvert)				(HWM .3m) 02/03/12 HWM not visible at this inspection.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	NONE			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	77.8/77.8	Sufficiency Rating (Last/Now) (%)	75.2/74.8	Est. Repl. Yr	2040	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Tim Davies		Previous Assistant's Name				
Next Inspection Date	19-Jun-2015		Previous Inspection Date	11-Feb-2009			
Inspection Cycle (Default) (months)	39						
Comment							