						Bridge I	nspe	ction								
Bridge File Nur	nber	84031 -	1 Bridge				Form Type				SS					
Year Built/Year									3							
Supstr				-					Lot No. Inspector Name			Garry Roberts				
Bridge or Town Name CALGARY							· · ·	Inspector Class			BR CLS A					
Located Over	S-NI			Assistant Name												
Located On	3		Ass	istant	Class											
Water Body Cl.							02-Oct-2010									
Navigabil. Cl./Y	'ear							B			Alyssa Boynton					
Legal Land Location SE SEC 6 TWP 23 RGE 1 W5M							, ,				22-Oct-2010					
Longitude, Latitude -114:07:22, 50:55:41											Tom Carey					
Road Authority Alberta Transportation (AIT)						Review Date					06-Oct-2010					
Contract Main.	Area	UNDEF	INED CM/	۹		Dept. Reviewer Nar				me						
Clear Roadway	//Skew	2.3 /				Dept. Review Date					27-Oct-2010					
AADT/Year						· · ·				27-001-2010						
Road Classifica	ation							Follow-Up By								
Detour Length	(km)															
Allowable Load	l (t): Sin	ngle			Semi			Train				> On Criti	cal Spans ⁄Iember			
Design Loading	g:											> Primary Span				
					P	osting I	nforn	nation								
Required Load Posting (t) Sir					Single			Semi			Truck Train					
Posted Loading (t)				Single				Semi			Truck Train					
Posted:	Lane	NB		At Junction (Y/N)		No		In Advance (Y/N)		No	At Bridge (Y/N)		No			
Posted:	Lane	SB At Junction ()			ion (Y/N)	No		In Advance (Y/N)		No	At Bridge (Y/N)		No			
Remarks	Not re	equired														
Hazard Marker	At Bride	ge (Y/N)	No													
Remarks Not required																
Other Sign Types Bridge #9																
					U	tilities (	Locat	ted at)								
Utility Attachme	ents															
Telephone							Gas	5								
Power	East					Munici										
Others							Problem (Y/N) No									
Remarks																
						Approa	ach R	oad								
					Las				on of Co	ondi	tion					
Horizontal Aligi	nment				5	5	Ped	lestriar	n path br	idge	#9					
Vertical Alignm	ent			5			unt	to 300	mm ∆C⊑	) ero	ded @ east a	side c	of path @ Nor	th		
Roadway Widtl	n (m)		2.300							010						
Approach Bum			2.000		5		1									
		No	5		6											
			X	X												
Guardrail			^	~												
Length (m) Current Stan	dard (V/	(NI)	No				-									
		14)					-									
Termination Type Drainage					7	7										
	1.0					-	-									
Approach Roa	id Gene	eral Ratir	ng		5	5										

onent				Last	Now	Explanation of Condition
n : SSF, 1 Spa	ins, Le	ngths(	m): 24.3, A-Id	ent Nu	mber:	
ures						
ire					Х	
ire					Х	
				1		
ace/Deck Top	Detail I	Ratings				
				3 (%)		
	. (, . ,		_ (//)			
0.0	0	.0	0.0	0	.0	
low 0.0 0.0 0.0						
(Material Type : COPPER CHROMATE ARSENATE TIMBER)						
mm) : <b>50</b> )						
				6	X	
lity				7	7	
				Х	Х	
e (deg. C)						
				1		
		Gap L	ocation			
		<u>- do -</u>				
e				7	7	
	1	No				
				X	X	
					~	
						-
icent Alea)				7	7	
				1	1	
1 -				-	-7	
	OT OT			/	/	
	SIST	=EL)		-	-	
				7	6	
NT)						
				Х	X	
				8	7	
				X	X	
				8	7	Welded connections
				8	7	Welded connections
				8	7	
1				8	7	
				8	7	
				Х	X	
Cross Frame				8	7	
	Jres re re ace/Deck Top N (%) 0.0 ace pe : COPPER mm) : 50) lity e (deg. C) Type : ) : ) m) stime e (deg. C) Type : ) : ) m) i : ) m) i : ) m) stime posts ST STEEL;PO posts Coating NT) None) rcent Area) i i i i i i i i i i i i i	Ires    re    ace/Deck Top Detail I    N (%)  1 (%)    0.0  0    ace  0.0    pe : COPPER CHRC    mm) : 50)  I    ity  I    e (deg. C)  1    Type : )  1    : )  1    nm)	Ires    re    ace/Deck Top Detail Ratings    N (%)  1 (%)    0.0  0.0    ace    pe : COPPER CHROMATE    mm) : 50)	Iree    re    ace/Deck Top  Detail Ratings    N (%)  1 (%)  2 (%)    0.0  0.0  0.0    0.0  0.0  0.0    ace  2 (%)    pe :  COPPER CHROMATE ARSENATE *    mm) :  50)	res  i    re  i    ace/Deck Top Detail Ratings  3 (%)    0.0  0.0  0.0    0.0  0.0  0.0    ace  X    pe : COPPER CHROMATE ARSENATE TEXT    mm) : 50)  i    iity  7    fity  7    re (deg. C)  i  X    rype : )  i  X    rype : )  i  X    rype : )  Gap Location  X    rype : )  Gap Location  X    rype : )  i  X    rype : )  Gap Location  X    rype : )  i  X    rype : )  i	re kin kie

Alberta Transportation

			Supers	structure
Bridge Component		Last		Explanation of Condition
(Primary Span : SSF, 1 Spans,	Lengths(m): 24.3, A-lo	dent Nu	umber:	)
Paint Condition		5	5	
(Colour Description : BROWN	)			
(Colour Code : <b>30252</b> )				
Touchup Required (Y/N)	No			
Bearings		7	7	
Temperature (deg. C)	20			
(Expansion Type : SLIDING P	LATE)			
(Fixed Type : )				
Coating Adequate (Y/N)	Yes			
Functioning (Y/N)	Yes			
Deck Underside		8	7	
Stains (Percent Area)	10			
(Snow Slots Filled : )				
Span Alignment Problems				
Vertical (Y/N)	No			
Horizontal (Y/N)	No			
Superstructure General Rating	g	7	7	
	-			
Bridge Component Abutments		Last	Now	Explanation of Condition
Bearing Seats/Caps/Corbels		N	N	Buried at both ends
(Type : TREATED TIMBER)			IN	
(Depth(mm) : )				-
(Width(mm) : )				-
Backwalls/Breastwalls		7	5	
Wingwalls		4	5	
Piles		N	Х	
Paint/Coating		X	X	
Abutment Stability		7	5	
Scour/Erosion		7	7	
Piers/Bents				
(Type : )				-
Bearing Seats/Caps/Corbels		X	X	
(Type : )				
(Total Number of Bearing Piles	)			-
Pier Shaft/Piles		X	X	
Greatest Height (m)				
Bracing/Struts/Sheathing		X	X	
Nose Plate		Х	Х	
Paint/Coating		X	X	
(Colour Description : )				
(Colour Code : )				
Pier Stability		X	Х	

## Alberta Transportation

			Subst	ructure
Bridge Component		Last	Now	Explanation of Condition
Scour		X	X	
Debris (Y/N)	No			
Substructure General Rating		7	5	
		S	Structu	re Usage
		Last	Now	Explanation of Condition
Channel				
(U/S Direction : W)				On curve
(D/S Direction : E)				
Alignment		4	5	
Bank Stability		5	5	Cut banks u/s and d/s
HWM (m below Top of Curb)	2.5			No visible HWM
Drift (Y/N)	No			
Slope Protection		4	6	
(Type : <b>RIP RAP; RIP RAP</b> )				
Guidebank/Spurs		X	Х	
Adequacy of Opening		5	6	
(Fish Compensation Measure 1	: NONE)			
(Fish Compensation Measure 2	2 : NONE)			
Channel General Rating		4	5	

Maintenance Recommendations													
Inspector Recommendations		Year	Inspector	r Comments			Department Co	ommer	nts		Target Year	Est. Cost	Cat #
REPAIR/REPLACE BRIDGE RAIL													
GALVANIZE/PAINT BRIDGE RAIL													
RETROFIT BRIDGE RAIL													
SEAL CURBS													
PATCH DECK													
SEAL DECK													
OVERLAY DECK													
REPAIR/REPLACE DECK JOINTS													
RESET/ PAINT BEARINGS													
REPAINT SUPERSTRUCTURE													
STRAIGHTEN/REPLACE MEMBERS													
WASHING													
SHOTCRETE REPAIRS													
REPAIR ABUTMENT SCOUR/EROSIC	ON												
PLACE ADDITIONAL RIP RAP													
REMOVE DRIFT ACCUMULATION													
OTHER ACTION		2011 Remove dirt and grass around abuts. and bearings											
OTHER ACTION													
OTHER ACTION													
OTHER ACTION													
Structural Condition Rating (Last/No (%)	ow)	77.8/66.	7	Sufficiency Rating (Last/Now) (%)		69.7/81.5		Est. Repl. Yr		2040	Maint. Re	eqd. (Y/N) Yes	
Special Comments for Next Inspection							Department Comments						
Maintenance Reviewed By							Date			E	Estimated Total	0	
Proposed Long-Term Strategy													
On 3-Year Program (Y/N)													
Proposed Action													
Previous Inspector's Name Tom 0		arey			Previou	vious Assistant's Name							
Next Inspection Date 02-Ju					Previou	revious Inspection Date 22-Jun-2005							
Inspection Cycle (Default) (months) 57													
Comment													