

Bridge Inspection										
Bridge File Number	84053 -1 Bridge				Form Type	SG				
Year Built/Year Supstr	1988/1988				Lot No.	2				
Bridge or Town Name	CANMORE				Inspector Name	Garry Roberts				
Located Over	WATERCOURSE, WATERCRS-NI				Inspector Class	BR CLS A				
Located On	TRAIL-PED, ON 50000 FB				Assistant Name					
Water Body Cl./Year					Assistant Class					
Navigabil. Cl./Year					Inspection Date	20-Jul-2012				
Legal Land Location	SE SEC 1 TWP 25 RGE 11 W5M				Data Entry By	Kelsey Roberts				
Longitude, Latitude	-115:23:55, 51:05:58				Data Entry Date	27-Aug-2012				
Road Authority	Alberta Transportation (AIT)				Reviewer Name	Tom Carey				
Contract Main. Area	UNDEFINED CMA				Review Date	27-Jul-2012				
Clear Roadway/Skew	4.6 /				Dept. Reviewer Name	Tim Davies				
AADT/Year					Dept. Review Date	06-Sep-2012				
Road Classification	RLU-208G-60				Follow-Up By					
Detour Length (km)	1									
Allowable Load (t):	Single		Semi		Train		----> On Critical Spans ---->Critical Member			
Design Loading:								----> Primary Span		

Posting Information									
Required Load Posting (t)	Single				Semi		Truck Train		
Posted Loading (t)	Single				Semi		Truck Train		
Posted:	Lane	NB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Posted:	Lane	SB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Remarks	Not req.								
Hazard Marker At Bridge (Y/N)	No								
Remarks	Not req.								
Other Sign Types									

Utilities (Located at)										
Utility Attachments										
Telephone					Gas					
Power					Municipal					
Others					Problem (Y/N)	No				
Remarks										

Approach Road									
		Last	Now	Explanation of Condition					
Horizontal Alignment		5	5	50m South of Jct.#58 NC 10					
Vertical Alignment		5	5						
Roadway Width (m)	4.000			Gravel path					
Approach Bump		6	5						
Guardrail (Y/N)	Yes			Missing and broken post at NE					
Guardrail		X	3						
Length (m)	4.000								
Current Standard (Y/N)	Yes								
Termination Type	End Post								
Drainage		7	7						
Approach Road General Rating		5	5						

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Primary Span : RB, 2 Spans, Lengths(m): 14.6-14.6, A-Ident Number:)					
Special Features					
Special Feature			X		
(Type :)					
Special Feature			X		
(Type :)					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
Last	0	0	0	0	
Now	0.0	0.0	0.0	0.0	
Wearing Surface			7	7	75x250 CCA
(Material Type : COPPER CHROMATE ARSENATE TREATED TIMBER)					
(Thickness(mm) : 75)					
Deck Top			7	7	
Deck Rideability			7	7	
Deck Joints			X	7	
Temperature (deg. C)		25			
(Expansion Type : BUFFER ANGLES)					
(Fixed Type : BUFFER ANGLES)					
Gap Size (mm)		Gap Location			
Deck Drainage			8	X	
Drains Clogged (Y/N)					
Curbs/Median			X	X	
(Curb Type : Standard)					
Scaling (Percent Area)					
Bridge Rail			5	6	Minor damage @ SE
(Type : TREATED TIMBER BRIDGE SOLID BEAM (EX. TIMBER RAILS))					
Bridge Rail Posts			7	7	5% failed
(Type : TREATED TIMBER;TREATED TIMBER)					
Bridge Rail/Posts Coating			5	5	
(Type : PAINT)					
Sidewalk			X	X	
Girder/Beam					
Cover Plate			X	X	Spliced over pier
Flange			9	8	
Web			9	8	
Stiffeners			X	X	
Splice			9	8	
Weld			X	X	
Diaphragms/Cross Frame			9	8	

Superstructure				
Bridge Component		Last	Now	Explanation of Condition
(Primary Span : RB, 2 Spans, Lengths(m): 14.6-14.6, A-Ident Number:)				
Paint Condition		8	7	
(Colour Description : BROWN)				
(Colour Code : 30252;)				
Touchup Required (Y/N)	No			
Bearings		8	7	A1 and A2 AT Pier
Temperature (deg. C)	26			
(Expansion Type : REINFORCED PAD BEARING)				
(Fixed Type : STEEL SLIDING PLATES WITH BRONZE PLATE IN BETWEEN)				
Coating Adequate (Y/N)	Yes			
Functioning (Y/N)	Yes			
Deck Underside		8	7	150x150 CCA timber
Stains (Percent Area)				
Span Alignment Problems				
Vertical (Y/N)	No			
Horizontal (Y/N)	No			
Superstructure General Rating		8	7	
Substructure				
Bridge Component		Last	Now	Explanation of Condition
Abutments				
Bearing Seats/Caps		8	8	
(Type : CONCRETE)				
Backwalls/Breastwalls		8	8	
Wingwalls		8	8	
Piles		N	N	
Paint/Coating		X	X	
Abutment Stability		9	8	
Scour/Erosion		9	7	
Piers/Bents				
(Type : PIER-COLUMN)				
Bearing Seats/Caps		8	8	
(Type : STEEL)				
(Total Number of Bearing Piles : 2)				
Pier Shaft/Piles		8	8	
Bracing/Struts/Sheathing		X	X	
Nose Plate		X	X	
Paint/Coating		X	X	
(Colour Description :)				
(Colour Code :)				
Pier Stability		8	8	
Scour		8	5	Minor erosion starting at East column
Debris (Y/N)	No			

Substructure				
Bridge Component		Last	Now	Explanation of Condition
Substructure General Rating		8	8	
Structure Usage				
		Last	Now	Explanation of Condition
Channel				
(U/S Direction : W)				
(D/S Direction : E)				
Alignment		7	7	
Bank Stability		5	4	Steep cut at SW
HWM (m below Top of Curb)	6.0			No Visible HWM Trees @ banks and streambed
Drift (Y/N)	Yes			
Slope Protection		5	5	
(Type : RIP RAP; RIP RAP)				
Guidebank/Spurs		X	X	
Adequacy of Opening		8	8	
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	4	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL	2012	Install approach rail at NE- 4.5m CCA rail and post.					
GALVANIZE/PAINT BRIDGE RAIL							
RETROFIT BRIDGE RAIL							
SEAL CURBS							
PATCH DECK							
SEAL DECK							
OVERLAY DECK							
REPAIR/REPLACE DECK JOINTS							
RESET/ PAINT BEARINGS							
REPAINT SUPERSTRUCTURE							
STRAIGHTEN/REPLACE MEMBERS							
WASHING							
SHOTCRETE REPAIRS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	88.9/83.3	Sufficiency Rating (Last/Now) (%)	/85.9	Est. Repl. Yr	2050	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Tom Carey		Previous Assistant's Name				
Next Inspection Date	20-Apr-2017		Previous Inspection Date	17-Jul-2007			
Inspection Cycle (Default) (months)	57						
Comment							