Bridge Culvert Inspection														
Bridge File Num	ber 84	105 -2	2 Bridge Culve	rt			Form Type			CUL1				
Year Built 2010						Lot No.			4					
Bridge or Town Name PEDESTRIAN UNDERPASS O			N WES	T-	Inspecto	or Name		Tom Carey						
SOUTH RAMP OF TWP 261 & F				HVVY 2		Inspecto	or Class		BR CLS A					
Located Over TRAIL-PED						Assistar	t Name							
Located On FUTURE W-S RAMP						Assistar	t Class							
Water Body CI./	Year						Inspection	on Date		28-Oct-2011				
Navigabil. CI./Ye	ear	050					Data En	try By		Alyssa Boynton				
Legal Land Loca	ation INE	SEC	1 TWP 26 RG				Data En	try Date		18-Nov-2011				
Longitude, Latitu	ude -11	4:00:	17, 51:11:52 Transmontation				Reviewe	er Name		Garry Roberts				
Contract Main				(AIT)			Review	Date		02-Nov-2011				
Clear Boodwow							Dept. Re	eviewer N	Name	Tim Davies				
	Skew 10		≠y. 2011 (⊑)				Dept. Re	Dept. Review Date 21-Nov-2011						
Road Classificat	tion RI	11-208	8-100				Follow-Up By							
Detour Length (km) 3	0-200	0-100											
Bridge Culvert	Informatio													
Number of Culv	erts		1											
Pipe #	Barrel		Span	Rise (or Dia.)		Туре		Length		Corr. Profile	PI./Slab	Shape		
1	MAIN		4200	3600		PCB		22.5				RECTANGLE		
Special Feature	s	F	BARREL LIGH	ITING										
Special Feature	s Commen	nt												
•														
			ĺ		Ро	sting Ir	nformatio	on						
Required Vert. (Clearance	Postir	ng (m)											
Posted Vertical Clearance (Y/N)														
Posted: Lane	NB	On B	Bridge (m)	In Adv	ance (Y/N)	La	ne SB	0	n Bridge (m)	In Advar	nce (Y/N)		
Remarks														
Utility Attachme	nts				Uti	lities (L	Located a	it)						
Telephone							Gas							
Power	Multiple w	ble wires to East.					Municipa	al						
Others	Light stan	standards.					Problem (Y/N) No							
Remarks	Storm wa	ter po	ond to NE											
				Ap	oproac	h Road	d / Emba	nkment						
					Last	Now	Explanation of Condition							
Horizontal Align	ment					7	Curve	Curve						
Vertical Alignment					7	Grade	Grade							
Roadway Width (m) 9.200						One way W/B on road above. 3.2m wide A.C.P pedway underneath.								
Embankment					8									
Sideslope (:1)														
(Height of Cover(m) : 1.8)														
Guardrail (Y/N) Yes					At East only.									
Approach Road / Embankment General Rating				7										
						Upstre	am End							
Culvert Component				Last	Now	Explanation of Condition								
Direction				W		West								
End Treatment (Concrete, Steel, CONCRETE Others, None)			=											
. /						1	1							

Alberta Transportation

Upstream End									
Culvert Component		Last	Now	Explanation of Condition					
Collar			Х						
Wingwalls			9						
(Shape : FLARE)									
Cutoff Wall			X						
Bevel End			Х						
Heaving (mm)									
Invert Above/Below Stream Bed									
Above/Below (mm)									
Scour Protection			X						
(Type : NATURAL)				_					
(Avg. Rock Size(mm) :)			-						
Scour/Erosion			X						
Beavers (Y/N)									
Upstream End General Rating	1		9						
		Bric	lge Cu	lvert Barrel					
Culvert Component Last Now Explanation of Condition									
(Pipe # : 1, Primary Span, Loca	tion Code: MAIN, Spa	n (mm)): 4200), Rise (mm): 3600, Type: PCB)					
Barrel Last Accessible Date	28-Oct-2011								
Special Features									
Special Feature			8	Safety rail on wingwalls.					
(Type : BARREL LIGHTING)			-						
Special Feature									
(Type :)									
Roof			8	A.C.P to roof for reference.					
Measured Rise (mm)	3517								
Measured At Ring No.	8								
Sag (mm)	0			-					
Percent Sag	0								
Sidewall			8						
Measured Span (mm)	4210								
Measured At Ring No.	8			-					
Deflection (mm)	0								
Percent Deflection	0								
Floor			N	80mm ACP covered.					
Bulge (mm)									
Measured At Ring No.									
Abrasion (Y/N)									
Circumferential Seams			6	Roto foam sealed.					
Separation (mm)	12			As much as 25mm horizontal misalignment.					
Longitudinal Seams			Х						
Total No. of Cracked Rings									
Total No. of Rings with Two Cracked Seams									
Min. Remaining Steel Between Cracks (mm)									
Proper Lap (Y/N)				1					
Longitudinal Stagger (Y/N)				1					

Alberta Transportation

Bridge Inspection & Maintenance System (Web 2005)

		Bric	lge Cu	vert Barrel
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Loca	tion Code: MAIN, Spa	n (mm): 4200	, Rise (mm): 3600, Type: PCB)
Coating			X	No coating at box or wings.
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)				
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N) No				
Fish Passage Adequacy			X	
Baffle			X	
(Туре:)		1		
Waterway Adequacy			X	
Icing (Y/N)				
Silting (Y/N)				
Drift (Y/N)				
Barrel General Rating			8	
		D	ownstr	eam End
Culvert Component		Last	Now	Explanation of Condition
Direction		E		East
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall			8	Staining.
Collar			Х	
Wingwalls			9	
(Shape : FLARE)				
Cutoff Wall			Х	
Bevel End			X	
Heaving (mm)				
Invert Above/Below Stream Bed				
Above/Below (mm)				
Scour Protection			X	
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion			Х	
Beavers (Y/N)				
Downstream End General Ration	ng		8	
		S	tructu	re Usage
		Last	Now	Explanation of Condition
Grade Separation				
Road Alignment			X	3.2m wide pedway flares to 4.1m wide in box.
Roadway Surface			8	
(Type : ACP)				
Icing (Y/N)	No			
Traffic Safety Features			Х	
Туре				

Structure Usage								
		Last	Now	Explanation of Condition				
Lighting			9	2 lights in box at Southside.				
Barrel Leakage (Y/N)	No							
Drainage			8					
Structure In Use (Y/N)	Yes							
Grade Separation General Rating			8					

Maintenance Recommendations											
Inspector Recommendations		r	Inspector Comments	Department Com	ments	Target Year	Est. Cost	Cat #			
SHOTCRETE REPAIRS											
PLACE ADDITIONAL RIP RAP											
REMOVE DRIFT ACCUMULATION											
INSTALL CONCRETE/STEEL LINING											
INSTALL STRUTS											
INSTALL CONCRETE COLLAR/CUTO	FF										
REPAIR SEAMS											
OTHER ACTION											
OTHER ACTION											
OTHER ACTION											
OTHER ACTION											
Structural Condition Rating (Last/Now) (%)		9	Sufficiency Rating (Last/Now) (%)	/92.1	/92.1 Est. Repl. Yr 206		Maint. Re	qd. (Y/N)	No		
Special Comments for Next Inspection				Department Comments							
Maintenance Reviewed By				Date		E	Estimated Total	0			
Proposed Long-Term Strategy											
On 3-Year Program (Y/N)											
Proposed Action											
Previous Inspector's Name			Previous	s Assistant's Name							
Next Inspection Date	28-Jul-2013	;	Previous	us Inspection Date							
Inspection Cycle (Default) (months)	21										
Comment											