

Bridge Culvert Inspection			
Bridge File Number	00854 -1 Bridge Culvert	Form Type	CUL1
Year Built	1961	Lot No.	4
Bridge or Town Name	AIRDRIE	Inspector Name	Garry Roberts
Located Over	TRIBUTARY TO NOSE CREEK, 2.13.32.5, WATERCRS-ST	Inspector Class	BR CLS A
Located On	567:04 C1 3.436	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	25-Jul-2012
Legal Land Location	SW SEC 17 TWP 27 RGE 1 W5M	Data Entry By	Lauren Korte
Longitude, Latitude	-114:06:60, 51:18:01	Data Entry Date	30-Aug-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Tom Carey
Contract Main. Area	CMA29	Review Date	07-Aug-2012
Clear Roadway/Skew	9.2 / 45 deg. (RHF)	Dept. Reviewer Name	Tim Davies
AADT/Year	2,240 / 2011 (A)	Dept. Review Date	06-Sep-2012
Road Classification	RLU-209-110	Follow-Up By	
Detour Length (km)	6		

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	2027	2241	SPE	43.9	152X51	3.0	ELLIPSE
Special Features								
Special Features Comment								

**Utilities (Located at)**

Utility Attachments			
Telephone	South ditch.	Gas	
Power	North ROW.	Municipal	
Others		Problem (Y/N)	No
Remarks			

**Approach Road / Embankment**

	Last	Now	Explanation of Condition
Horizontal Alignment	7	7	Access road both sides of pipe. Hill to West.
Vertical Alignment	7	6	
Roadway Width (m)	9.200		
Embankment	7	7	
Sideslope ( __:1)	2.0		
(Height of Cover(m) : 3)			
Guardrail (Y/N)	No		
<b>Approach Road / Embankment General Rating</b>	<b>7</b>	<b>6</b>	

**Upstream End**

Culvert Component	Last	Now	Explanation of Condition
Direction	N		North.
End Treatment (Concrete, Steel, Others, None)	CONCRETE		
Headwall	X	X	
Collar	X	X	
Wingwalls	X	X	
(Shape : )			
Cutoff Wall	7	6	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		7	7	
Heaving (mm)	300			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	150			
Scour Protection		7	7	
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>300</b> )				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>7</b>	<b>6</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2027, Rise (mm): 2241, Type: SPE)				
Barrel Last Accessible Date	25-Jul-2012			
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		4	4	Roof distortion based on 100mm floor bulge not being @ mid. Rated 4 due to cracks in circumferential seams.
Measured Rise (mm)	2112			
Measured At Ring No.	8			
Sag (mm)	129			
Percent Sag	5			
Sidewall		6	6	Slight curve in barrel.
Measured Span (mm)	2125			
Measured At Ring No.	8			
Deflection (mm)	98			
Percent Deflection	4			
Floor		5	5	
Bulge (mm)	100			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		4	4	SEAMS #5 to #10 HAVE 1 CRACK AT TOP ROOF BOLT. Cracks appear to have stabilized.
Separation (mm)	0			
Longitudinal Seams		5	5	Loose bolts throughout crack at roof bolt in Ring 14 (appear to be installation damage).
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			Crack bolts in circ seams not long seam. 1N stagger.
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	Yes			
Coating		5	5	Alkali and rust at bolt holes of lower seams only with minor scale buildup.
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2027, Rise (mm): 2241, Type: SPE)				
Fish Passage Adequacy		5	5	
Baffle		X	X	
(Type : )				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>4</b>	<b>4</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		South.
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		6	6	Only top is visible.
Bevel End		7	7	
Heaving (mm)	200			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	200			
Scour Protection		5	5	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 250)				
Scour/Erosion		5	5	Minor rock lined scour @ SW.
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>7</b>	<b>5</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel (U/S and D/S)</b>				
Alignment		6	6	
Bank Stability		7	7	
HWM (m below Top of Culvert)				NO HWM VISIBLE.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	DEGRADING			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
<b>Channel General Rating</b>		<b>6</b>	<b>6</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>44.4/44.4</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>58.0/55.4</b>	Est. Repl. Yr	2025	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name				
Next Inspection Date	25-Oct-2015		Previous Inspection Date	14-May-2009			
Inspection Cycle (Default) (months)	39						
Comment							