

Bridge Culvert Inspection				
Bridge File Number	86151 -2 Bridge Culvert		Form Type	CUL1
Year Built	2008		Lot No.	4
Bridge or Town Name	MANNING		Inspector Name	Brian Pientsch
Located Over	WATERCOURSE, WATERCRS-NI		Inspector Class	BR CLS A
Located On	691:02 C1 6.258		Assistant Name	Brian Cote
Water Body Cl./Year			Assistant Class	BR CLS B
Navigabil. Cl./Year			Inspection Date	19-Mar-2013
Legal Land Location	SE SEC 30 TWP 91 RGE 22 W5M		Data Entry By	Lisa Fairhurst
Longitude, Latitude	-117:31:35, 56:54:55		Data Entry Date	08-Apr-2013
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Eric Carcoux
Contract Main. Area	CMA04		Review Date	08-Apr-2013
Clear Roadway/Skew	9.5 / 10 deg. (RHF)		Dept. Reviewer Name	
AADT/Year	470 / 2012 (A)		Dept. Review Date	
Road Classification	RCU-208-110		Follow-Up By	
Detour Length (km)	6			

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	-	1829	SSP	37		12.7	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)			
Utility Attachments			
Telephone	S. r of w		Gas
Power	5 wire OH N r of w		Municipal
Others			Problem (Y/N) No
Remarks			

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	Approach 10m W on North side
Vertical Alignment		8	8	
Roadway Width (m)	9.500			
Embankment		7	7	
Sideslope (_ :1)	4.0			
(Height of Cover(m) : 2.2)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		7	7	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		8	8	50% visible
Heaving (mm)				
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		8	N	Snow covered
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		8	N	
Beavers (Y/N)	No			Snow covered
Upstream End General Rating		8	8	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1 , Primary Span, Location Code: MAIN , Span (mm): , Rise (mm): 1829 , Type: SSP)				
Barrel Last Accessible Date	19-Mar-2013			1678mm ice to crown
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		8	8	
Measured Rise (mm)	1829			near cl - 21 Oct 2009
Measured At Ring No.				
Sag (mm)				
Percent Sag				
Sidewall		8	8	
Measured Span (mm)	1835			near cl
Measured At Ring No.				
Deflection (mm)	6			
Percent Deflection	0			
Floor		8	8	Sections with ice/dirt on floor
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		8	8	
Separation (mm)				
Longitudinal Seams		8	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		8	8	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1829, Type: SSP)				
Fish Passage Adequacy		8	8	
Baffle		X	X	
(Type :)				
Waterway Adequacy		8	8	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		8	8	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		8	8	30% visible
Heaving (mm)				
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	450			
Scour Protection		8	N	Snow covered
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		8	N	Snow covered
Beavers (Y/N)	No			
Downstream End General Rating		8	8	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	7	
Bank Stability		7	7	
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)				
Channel Bottom Degrading/Aggrading				
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	88.9/88.9	Sufficiency Rating (Last/Now) (%)	87.1/87.2	Est. Repl. Yr	2058	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date		Estimated Total	0	
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Eric Caroux		Previous Assistant's Name				
Next Inspection Date	19-Jun-2016		Previous Inspection Date	21-Sep-2009			
Inspection Cycle (Default) (months)	39						
Comment							