

Bridge Culvert Inspection			
Bridge File Number	86280 -1 Bridge Culvert	Form Type	CUL1
Year Built/Lined	2011/2011	Lot No.	4
Bridge or Town Name		Inspector Name	Brian Pientsch
Located Over	WATERCOURSE, WATERCRS-NI	Inspector Class	BR CLS A
Located On	2:60 C1 25.525	Assistant Name	Clem Guenette
Water Body Cl./Year		Assistant Class	BR CLS B
Navigabil. Cl./Year		Inspection Date	27-Nov-2012
Legal Land Location	NE SEC 6 TWP 83 RGE 20 W5M	Data Entry By	Theresa Lacusta
Longitude, Latitude	-117:08:45, 56:10:07	Data Entry Date	24-Jan-2013
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Eric Carcoux
Contract Main. Area	CMA04	Review Date	09-Jan-2013
Clear Roadway/Skew	11.8 /	Dept. Reviewer Name	David Morrison
AADT/Year	2,960 / 2011 (A)	Dept. Review Date	21-Mar-2013
Road Classification		Follow-Up By	
Detour Length (km)			

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
2	MAIN FULL LINER	-	760	SSP	30		3.0	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone	East r/w.	Gas	
Power		Municipal	
Others		Problem (Y/N)	No
Remarks			

Approach Road / Embankment

	Last	Now	Explanation of Condition
Horizontal Alignment		6	Approach 150m N. curve 40m S.
Vertical Alignment		8	
Roadway Width (m)	11.800		
Embankment		7	
Sideslope (:1)	4.0		
(Height of Cover(m) : 2.5)			
Guardrail (Y/N)	No		
Approach Road / Embankment General Rating		6	

Upstream End

Culvert Component	Last	Now	Explanation of Condition
Direction	E		
End Treatment (Concrete, Steel, Others, None)	STEEL		
Headwall		X	
Collar		X	
Wingwalls		X	
(Shape :)			
Cutoff Wall		X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End			7	
Heaving (mm)				
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	100			
Scour Protection			7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion			7	
Beavers (Y/N)	No			
Upstream End General Rating			7	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2 , Secondary Span, Location Code: MAIN , Span (mm): , Rise (mm): 760 , Type: SSP)				
Barrel Last Accessible Date				Ice to roof = 290mm Unable to inspect barrel.
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof			N	
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)				
Percent Sag				
Sidewall			N	
Measured Span (mm)				
Measured At Ring No.				
Deflection (mm)				
Percent Deflection				
Floor			N	
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams			X	
Separation (mm)				
Longitudinal Seams			X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating			N	
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)				
Camber POS/ZERO/NEG				
Ponding (Y/N)				

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 760, Type: SSP)				
Fish Passage Adequacy			5	
Baffle			X	
(Type :)				
Waterway Adequacy			6	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating			N	Unable to rate due to ice.
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall			X	
Collar			X	
Wingwalls			X	
(Shape :)				
Cutoff Wall			X	
Bevel End			7	
Heaving (mm)				
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	100			
Scour Protection			7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion			7	
Beavers (Y/N)	No			
Downstream End General Rating			7	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment			5	Water turns 90 degree d/s.
Bank Stability			7	
HWM (m below Top of Culvert)				HWM not visible
Drift (Y/N)	Yes			Some at u/s end
Channel Bottom Degrading/Aggrading				stable
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating			5	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	/55.6	Sufficiency Rating (Last/Now) (%)	/57.9	Est. Repl. Yr	2061	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name			Previous Assistant's Name				
Next Inspection Date	27-Aug-2014		Previous Inspection Date				
Inspection Cycle (Default) (months)	21						
Comment							