

Bridge Culvert Inspection			
Bridge File Number	09412 -1 Bridge Culvert	Form Type	CULM
Year Built	1954	Lot No.	4
Bridge or Town Name	HESPERO	Inspector Name	Owen Salava
Located Over	TRIBUTARY TO LASTHILL CREEK, 3.88.12.2, WATERCRS-ST	Inspector Class	BR CLS A
Located On	11:10 C1 47.671	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	01-Feb-2012
Legal Land Location	SE SEC 6 TWP 39 RGE 3 W5M	Data Entry By	Marcia Chavez
Longitude, Latitude	-114:24:56, 52:19:09	Data Entry Date	01-Mar-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	John O'Brien
Contract Main. Area	CMA18	Review Date	22-Feb-2012
Clear Roadway/Skew	18 / -45 deg. (LHF)	Dept. Reviewer Name	Andrew Smikles
AADT/Year	4,510 / 2010 (A)	Dept. Review Date	09-Mar-2012
Road Classification	RAU-211.8-110	Follow-Up By	
Detour Length (km)	6		

Bridge Culvert Information

Number of Culverts	2							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	1525	1525	MP	34.7	68X13	2.8	ROUND
2	MAIN	-	1200	MP	30	68X13	2.8	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone	North r/w. Fibre optic cable. South tel.	Gas	
Power	3 wires South r/w.	Municipal	
Others		Problem (Y/N)	No
Remarks			

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		9	9	
Vertical Alignment		8	8	
Roadway Width (m)	18.000			Includes passing lane for EB/WB.
Embankment		7	7	
Sideslope (__:1)	3.0			
(Height of Cover(m) : 1.7)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		8	8	

Upstream End

Culvert Component	Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)			
Direction	S		
End Treatment (Concrete, Steel, Others, None)	STEEL		
Headwall	X	X	
Collar	X	X	
Wingwalls	X	X	
(Shape :)			

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)				
Cutoff Wall		X	X	
Bevel End		5	5	Minor bend at top.
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		5	N	Snow covered.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 250)				
Scour/Erosion		5	N	
Beavers (Y/N)	No			
Upstream End General Rating		5	5	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1525, Rise (mm): 1525, Type: MP)				
Barrel Last Accessible Date	01-Feb-2012			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		6	6	
Measured Rise (mm)	1470			
Measured At Ring No.	2			
Sag (mm)	55			
Percent Sag	3			
Sidewall		6	6	Sweep to the West at North end.
Measured Span (mm)	1600			
Measured At Ring No.	2			
Deflection (mm)	75			
Percent Deflection	4			
Floor		N	6	
Bulge (mm)	25			
Measured At Ring No.	3			
Abrasion (Y/N)	No			
Circumferential Seams		5	5	South end seam.
Separation (mm)	80			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		5	5	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1525, Rise (mm): 1525, Type: MP)				
Camber POS/ZERO/NEG	POS			
Ponding (Y/N)	No			
Fish Passage Adequacy		6	6	
Baffle		X	X	
(Type :)				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		6	6	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)				
Direction		N		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		6	6	
Heaving (mm)	0			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	200			
Scour Protection		5	N	Snow covered.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 250)				
Scour/Erosion		5	N	
Beavers (Y/N)	No			
Downstream End General Rating		5	5	GR carried forward from 31Mar2010.
Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Secondary Span)				
Direction		S		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Secondary Span)				
Bevel End		5	5	Minor dent from installation.
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection		5	N	(Some Class I rocks. 31Mar2010). Snow covered.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 250)				
Scour/Erosion		5	N	
Beavers (Y/N)	No			
Upstream End General Rating		5	5	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1200, Type: MP)				
Barrel Last Accessible Date	01-Feb-2012			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		7	7	
Measured Rise (mm)	1230			
Measured At Ring No.	3			
Sag (mm)	30			
Percent Sag	2			
Sidewall		7	7	
Measured Span (mm)	1170			
Measured At Ring No.	3			
Deflection (mm)	30			
Percent Deflection	2			
Floor		N	6	Water covered.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		5	5	
Separation (mm)	110			
Longitudinal Seams		5	5	Riveted seam.
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		5	5	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	POS			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1200, Type: MP)				
Ponding (Y/N)	No			
Fish Passage Adequacy		6	6	
Baffle		X	X	
(Type :)				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		7	5	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Secondary Span)				
Direction		N		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		6	6	
Heaving (mm)	0			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	100			
Scour Protection		5	N	(Some Class I rock. 31Mar2010). Snow covered.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 250)				
Scour/Erosion		5	N	
Beavers (Y/N)	No			
Downstream End General Rating		5	5	GR carried forward from 31Mar2010.
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		8	8	
Bank Stability		8	8	
HWM (m below Top of Culvert)	0.7			
Drift (Y/N)	Yes			
Channel Bottom Degrading/Aggrading	DEGRADING			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		8	8	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	66.7/55.6	Sufficiency Rating (Last/Now) (%)	65.8/60.7	Est. Repl. Yr	2019	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Owen Salava		Previous Assistant's Name				
Next Inspection Date	01-Nov-2013		Previous Inspection Date	31-Mar-2010			
Inspection Cycle (Default) (months)	21						
Comment							