

Bridge Culvert Inspection			
Bridge File Number	09801 -1 Bridge Culvert	Form Type	CUL1
Year Built	1996	Lot No.	4
Bridge or Town Name	PLAMONDON	Inspector Name	Eric Carcoux
Located Over	TRIBUTARY TO PLAMONDON CREEK, 8.11.55.9.1.1, WATERCRS-ST	Inspector Class	BR CLS A
Located On	858:02 C1 6.806	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	30-Mar-2010
Legal Land Location	SW SEC 14 TWP 68 RGE 16 W4M	Data Entry By	Theresa Lacusta
Longitude, Latitude	-112:20:16, 54:52:49	Data Entry Date	27-Apr-2010
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Arnold Assenheimer
Contract Main. Area	CMA08	Review Date	19-Apr-2010
Clear Roadway/Skew	12 / -20 deg. (LHF)	Dept. Reviewer Name	Brent Herrick
AADT/Year	380 / 2009 (A)	Dept. Review Date	03-May-2010
Road Classification	RCU-209-110	Follow-Up By	
Detour Length (km)	50		

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	2200	MP	38	125X26	2.8	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)			
Utility Attachments			
Telephone	Along West ditch.	Gas	Along East ditch.
Power	2 wires OH 15m East of c/l.	Municipal	
Others		Problem (Y/N)	No
Remarks			

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		6	6	On curve.
Vertical Alignment		7	7	No passing, crest curve to South.
Roadway Width (m)	9.600			
Embankment		N	7	
Sideslope (__:1)	4.0			
(Height of Cover(m) : 2)				
Guardrail (Y/N)	No			
<b>Approach Road / Embankment General Rating</b>		<b>6</b>	<b>6</b>	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		Water to crown 800mm.
End Treatment (Concrete, Steel, Others, None)	STEEL			No evident problems.
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		N	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	500			
Scour Protection		N	7	
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>250</b> )				
Scour/Erosion		N	7	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>8</b>	<b>7</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : <b>1</b> , Primary Span, Location Code: <b>MAIN</b> , Span (mm): , Rise (mm): <b>2200</b> , Type: <b>MP</b> )				
Barrel Last Accessible Date	21-Mar-2002			Water to crown 800mm. shape looks good from ends.
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		N	N	
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)	70			(Est. 3.2% sag. 12/Mar/2002)
Percent Sag				
Sidewall		N	N	
Measured Span (mm)				
Measured At Ring No.				
Deflection (mm)	70			(3.2% deflection. 12/Mar/2002)
Percent Deflection				
Floor		N	N	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		N	N	
Separation (mm)	30			
Longitudinal Seams		X	X	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		7	N	
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2200, Type: MP)				
Fish Passage Adequacy		7	7	
Baffle		X	X	
(Type : )				
Waterway Adequacy		6	6	Iced over. Siltting -29-Nov-2006
Icing (Y/N)	No			
Siltting (Y/N)	Yes			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>N</b>	<b>N</b>	(General rating was "7". 12/Mar/2002)
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		Ice to crown 800mm. No evident problems.
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		N	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	500			
Scour Protection		N	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 250)				
Scour/Erosion		N	7	
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>8</b>	<b>7</b>	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		8	8	
Bank Stability		N	7	
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading				
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
<b>Channel General Rating</b>		<b>8</b>	<b>7</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>55.6/55.6</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>63.5/61.1</b>	Est. Repl. Yr	2047	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Jason Saly		Previous Assistant's Name				
Next Inspection Date	30-Jun-2013		Previous Inspection Date	29-Nov-2006			
Inspection Cycle (Default) (months)	39						
Comment							