


SITE NUMBER AND NAME C45 H9:04 Slides		HIGHWAY & KM	PREVIOUS INSPECTION DATE June 18, 2007	INSPECTION DATE June 13, 2008
LEGAL DESCRIPTION NE 35-28-20-W4	NAD 83 COORDINATES N 5699455 E 381200		RISK ASSESMENT PF: 9 CF: 2 TOTAL: 18	

SUMMARY OF SITE INSTRUMENTATION: None	INSPECTED BY: 
LAST READING DATE:	
PRIMARY SITE ISSUE: Slope Failures	
APPROXIMATE DIMENSIONS:	
DATE OF ANY REMEDIAL ACTION:	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress		X			X
Slope Movement	X		Surficial sloughing is occurring in the embankment above the highway. The highway is unaffected.		X
Erosion		X			X
Seepage		X			X
Culvert Distress		X			X

COMMENTS
Refer to attached photos.
It is recommended that the ditch be cleared regularly to prevent slough from blocking ditch flows.



