


SITE NUMBER AND NAME C36 H2A Gabion Drop		HIGHWAY & KM 1.6 km North of Innisfail	PREVIOUS INSPECTION DATE May 26, 2005	INSPECTION DATE May 16, 2006
LEGAL DESCRIPTION	NAD 83 COORDINATES N 5768712 E 299070	RISK ASSESMENT PF: 9 CF: 1 TOTAL: 9		

SUMMARY OF SITE INSTRUMENTATION: None	INSPECTED BY: 
LAST READING DATE:	
PRIMARY SITE ISSUE: Erosion around gabion drop structure	
APPROXIMATE DIMENSIONS:	
DATE OF ANY REMEDIAL ACTION: 2005 (additional baskets added)	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress					
Slope Movement					
Erosion	X		Approx. 3 m high gabion drop structure. Minor erosion is occurring around sides of structure.	X	
Seepage					
Culvert Distress					

COMMENTS
Refer to attached photos
The additional baskets have prevented the flows from going around the structure; however some movement of the rock upstream of the drop structure has occurred. It is recommended that either larger rock be provided or the gabion mat be extended upstream.







