

Slide Name: (GP 13) SH 722:02 Red Willow Creek
Inspection Date: N/A
Inspection By: N/A

1.0 BACKGROUND

Refer to EBA 2002 and earlier reports for site conditions and details of risk assessment. Some previous instrumentations were observed at this site during the 2000 annual site visit. No new instruments have been installed since 1996 (the onset of Regional Geotechnical Assignment). Attempts to locate information from previous instrumentation have not been successful.

2.0 OBSERVATIONS

- The site was not inspected during the 2003 annual inspection.
- Refer to previous observations as no obvious site deterioration was reported by MCI.

3.0 RISK ASSESSMENT

PF (5) * CF (3) = 15

Risk rating cannot be changed from the assessment in 2001.

4.0 ACTION

- As previously discussed with AT, it was recommended to incorporate the monitoring of the previous instrumentation with any new instrumentation which may be installed in the future as per previous site discussions.
- Maintenance forces are requested to record details of patch events (amount of settlement and quantity of patching) and submit the details for assessment.



Based on 1995 Aerial Photograph




Figure 1
SitePlan