

Bridge Culvert Inspection				
Bridge File Number	70874 E-1 Bridge Culvert		Form Type	CUL1
Year Built	1954		Lot No.	4
Bridge or Town Name	OBED		Inspector Name	Shane Hall
Located Over	PONOKA CREEK, 8.11.127, WATERCRS-ST		Inspector Class	BR CLS A
Located On	16:02 R1 49.404		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	11-Aug-2012
Legal Land Location	NE SEC 22 TWP 52 RGE 23 W5M		Data Entry By	Theresa Lacusta
Longitude, Latitude	-117:17:55, 53:30:39		Data Entry Date	09-Sep-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Eric Carcoux
Contract Main. Area	CMA13		Review Date	31-Aug-2012
Clear Roadway/Skew	12.2 / 0 deg.		Dept. Reviewer Name	Brent Herrick
AADT/Year	5,630 / 2011 (A)		Dept. Review Date	18-Sep-2012
Road Classification	RAD-412.4-120		Follow-Up By	
Detour Length (km)	1			

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	1724	1901	SPE	34.1	152X51	2.8	ELLIPSE
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments				
Telephone	North r/w		Gas	
Power	3 lines North r/w.		Municipal	
Others			Problem (Y/N)	No
Remarks				

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		8	8	EBL culvert. BF 80656 on WBL.
Vertical Alignment		8	8	
Roadway Width (m)	12.200			
Embankment		7	7	
Sideslope (__:1)	3.0			
(Height of Cover(m) : 1.5)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		8	8	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction		S		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		5	4	150mm tear in East side. Bevel starting to buckle at top due to uplift.
Heaving (mm)	750			
Invert Above/Below Stream Bed				
Above/Below (mm)				
Scour Protection (Type : NONE) (Avg. Rock Size(mm) :)		4	4	Bevel projecting approx 1m from fill, eroded along bottom edges. Fill settled up to 300mm along bevel sides. Bevel undermined for 1.5m.
Scour/Erosion		5	4	
Beavers (Y/N)	No			
Upstream End General Rating		4	4	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1724, Rise (mm): 1901, Type: SPE)				
Barrel Last Accessible Date	11-Aug-2012			
Special Features				
Special Feature (Type :)				
Special Feature (Type :)				
Roof		7	7	1st rings and bevel have uplifted close to 1m.
Measured Rise (mm)	1878			
Measured At Ring No.	8			
Sag (mm)	23			
Percent Sag	1			
Sidewall		7	6	Plates cusping @ 2:00 position in rings 5,6,7.
Measured Span (mm)	1730			
Measured At Ring No.	8			
Deflection (mm)	6			
Percent Deflection	1			
Floor		7	7	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	Yes			
Circumferential Seams		7	7	
Separation (mm)	0			
Longitudinal Seams		7	7	Piping through lower bolt holes in first 4 sections. 1N
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	Yes			
Coating		5	6	Superficial rusting on strip floor.-1m wide
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1724, Rise (mm): 1901, Type: SPE)				
Fish Passage Adequacy		4	4	Steep inlet end.
Baffle		X	X	
(Type :)				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	Yes			
Drift (Y/N)	No			
Barrel General Rating		7	6	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		Outlet flows from median and into BF 80656.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		7	6	
Heaving (mm)	0			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	100			
Scour Protection		7	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
Downstream End General Rating		7	6	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	7	
Bank Stability		7	7	
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	AGGRADING			Aggrading U/S due to heaved bevel.
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	77.8/66.7	Sufficiency Rating (Last/Now) (%)	66.4/59.8	Est. Repl. Yr	2030	Maint. Req. (Y/N)	No
Special Comments for Next Inspection	Monitor erosion and piping @ u/s end.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Eric Carcoux		Previous Assistant's Name				
Next Inspection Date	11-May-2014		Previous Inspection Date	15-Sep-2010			
Inspection Cycle (Default) (months)	21						
Comment							