

Bridge Culvert Inspection				
Bridge File Number	71539 -1 Bridge Culvert		Form Type	CUL1
Year Built	1977		Lot No.	4
Bridge or Town Name	JEFFERSON		Inspector Name	Jason Rusu
Located Over	2ND ORDER TRIBUTARY TO ROLPH CREEK, 2.12.20.10.4.1, WATERCRS-ST		Inspector Class	BR CLS B
Located On	820:02 C1 5.543		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	12-Jun-2010
Legal Land Location	NW SEC 31 TWP 1 RGE 23 W4M		Data Entry By	Erin Roberts
Longitude, Latitude	-113:04:39, 49:04:45		Data Entry Date	18-Aug-2010
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Garry Roberts
Contract Main. Area	CMA25		Review Date	18-Jul-2010
Clear Roadway/Skew	10 /		Dept. Reviewer Name	Lorenz Bohnert
AADT/Year	70 / 2009 (A)		Dept. Review Date	23-Aug-2010
Road Classification	RLU-209G-90		Follow-Up By	
Detour Length (km)	10			

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	1800	MP	25		3.5,3.5,3.5	ROUND
Special Features								
Special Features Comment								

**Utilities (Located at)**

Utility Attachments				
Telephone	W ditch		Gas	
Power	E side 1 wire N 2 wires S		Municipal	
Others			Problem (Y/N)	No
Remarks				

**Approach Road / Embankment**

		Last	Now	Explanation of Condition
Horizontal Alignment		9	9	Rises to the north Dip south.
Vertical Alignment		7	7	
Roadway Width (m)	9.400			
Embankment		8	8	
Sideslope ( _ :1)	3.0			
(Height of Cover(m) : 1.4)				
Guardrail (Y/N)	No			
<b>Approach Road / Embankment General Rating</b>		<b>7</b>	<b>7</b>	

**Upstream End**

Culvert Component		Last	Now	Explanation of Condition
Direction		E		U/S east.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		7	6	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		N	7	
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>300</b> )				
Scour/Erosion		N	7	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>7</b>	<b>6</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1800, Type: MP)				
Barrel Last Accessible Date	12-Jun-2010			
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		5	5	At midspan
Measured Rise (mm)	1694			
Measured At Ring No.				
Sag (mm)	106			
Percent Sag	6			
Sidewall		4	4	At midspan
Measured Span (mm)	1935			
Measured At Ring No.				
Deflection (mm)	135			
Percent Deflection				
Floor		N	6	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		6	6	No dirt infiltration - top = 10 mm, bottom = 50.
Separation (mm)	50			
Longitudinal Seams		X	X	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)	0			
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		6	6	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1800, Type: MP)				
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type : )				
Waterway Adequacy		8	8	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>4</b>	<b>4</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		West invert d/s.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	30			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	100			
Scour Protection		N	4	Missing rip rap to South of bevel
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 100)				
Scour/Erosion		N	4	Scour to South and D/S (3m x 5m x 1m deep)
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>7</b>	<b>4</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel (U/S and D/S)</b>				
Alignment		8	8	(Water backs up in the spring-told by farmer) 1-mar-2007 D/S minor.
Bank Stability		8	7	
HWM (m below Top of Culvert)				No visible HWM
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	DEGRADING			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
<b>Channel General Rating</b>		<b>8</b>	<b>8</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>44.4/44.4</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>66.9/63.1</b>	Est. Repl. Yr	2033	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date		Estimated Total	0	
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Tim Davies		Previous Assistant's Name				
Next Inspection Date	12-Sep-2013		Previous Inspection Date	01-Mar-2007			
Inspection Cycle (Default) (months)	39						
Comment							