

Bridge Culvert Inspection				
Bridge File Number	73572 -1 Bridge Culvert		Form Type	CUL1
Year Built	1984		Lot No.	4
Bridge or Town Name	GLEICHEN		Inspector Name	Jon Davies
Located Over	WID - IRRIGATION C, WATERCRS-IC		Inspector Class	BR CLS B
Located On	1:14 R1 25.610;1:14 L1 25.647		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	11-Feb-2012
Legal Land Location	SW SEC 6 TWP 23 RGE 22 W4M		Data Entry By	Lauren Korte
Longitude, Latitude	-113:04:29, 50:55:17		Data Entry Date	18-Mar-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Garry Roberts
Contract Main. Area	CMA30		Review Date	27-Feb-2012
Clear Roadway/Skew	25.4 / -25 deg. (LHF)		Dept. Reviewer Name	Tim Davies
AADT/Year	5,940 / 2010 (A)		Dept. Review Date	22-Mar-2012
Road Classification	RAD-412.4-120		Follow-Up By	
Detour Length (km)	1			

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	4353	3035	RPE	75.6	152X51		ELLIPSE
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone	East and West ROW.	Gas	
Power	1 wire West ROW and crossing 30 m North.	Municipal	
Others	Fibre optic cable at East ROW.	Problem (Y/N)	No
Remarks			

Approach Road / Embankment

	Last	Now	Explanation of Condition
Horizontal Alignment	6	6	Intersection immediately North. Crest curve to South. Turn out lanes over pipe.
Vertical Alignment	7	7	
Roadway Width (m)	26.800		
Embankment	7	6	
Sideslope (___:1)	4.5		
(Height of Cover(m) : 2.5)			
Guardrail (Y/N)	Yes		
Approach Road / Embankment General Rating	6	6	

Upstream End

Culvert Component	Last	Now	Explanation of Condition
Direction	W		West.
End Treatment (Concrete, Steel, Others, None)	CONCRETE		
Headwall	7	7	Some narrow cracks-minor.
Collar	7	7	
Wingwalls	X	X	
(Shape :)			
Cutoff Wall	N	N	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	400			
Scour Protection		6	5	Minor displacement at NW and SW.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 350)				
Scour/Erosion		6	5	
Beavers (Y/N)	No			
Upstream End General Rating		6	5	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 4353, Rise (mm): 3035, Type: RPE)				
Barrel Last Accessible Date	11-Feb-2012			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		N	7	Shape looks good.
Measured Rise (mm)				
Measured At Ring No.				Estimate.
Sag (mm)	100			
Percent Sag	3			
Sidewall		N	7	
Measured Span (mm)	4394			
Measured At Ring No.	10			
Deflection (mm)	41			
Percent Deflection	1			
Floor		N	N	Ice covered.
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		N	7	
Separation (mm)	0			
Longitudinal Seams		N	7	Seams not visible at lower sidewall and floor.
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams				3 N stagger at roof center.
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	No			
Coating		N	7	Minor staining at boltholes above waterline. Minor corrosion at waterline and below.
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 4353, Rise (mm): 3035, Type: RPE)				
Fish Passage Adequacy		8	7	
Baffle		X	X	
(Type :)				
Waterway Adequacy		7	6	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		N	7	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		East.
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		7	7	
Collar		7	7	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		N	N	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	600			
Scour Protection		7	6	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		7	6	
Beavers (Y/N)	No			
Downstream End General Rating		7	6	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		6	6	45 degree bend from NW to inlet.
Bank Stability		7	6	
HWM (m below Top of Culvert)	0.8			No visible HWM.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	AGGRADING			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		6	6	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	55.6/77.8	Sufficiency Rating (Last/Now) (%)	64.3/69.3	Est. Repl. Yr	2029	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name				
Next Inspection Date	11-Nov-2013		Previous Inspection Date	16-Jul-2010			
Inspection Cycle (Default) (months)	21						
Comment							