

Bridge Culvert Inspection			
Bridge File Number	73943 -2 Bridge Culvert	Form Type	CUL1
Year Built	2001	Lot No.	4
Bridge or Town Name	CRAIGMYLE	Inspector Name	Owen Salava
Located Over	TRIBUTARY TO BULLPOUND CREEK, 3.17.13, WATERCRS-ST	Inspector Class	BR CLS A
Located On	9:08 C1 38.351	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	02-Nov-2011
Legal Land Location	SW SEC 14 TWP 31 RGE 16 W4M	Data Entry By	Marcia Chavez
Longitude, Latitude	-112:10:03, 51:38:57	Data Entry Date	29-Nov-2011
Road Authority	Alberta Transportation (AIT)	Reviewer Name	John O'Brien
Contract Main. Area	CMA21	Review Date	14-Nov-2011
Clear Roadway/Skew	12.1 /	Dept. Reviewer Name	Andrew Smikles
AADT/Year	2,400 / 2010 (A)	Dept. Review Date	02-Dec-2011
Road Classification	RAU-211.8-110	Follow-Up By	
Detour Length (km)	70		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	2700	MP	36	125X26	3.5	ROUND
Special Features								
Special Features Comment	Cathodic protection/pole 14m N in ditch; not in service.							

Utilities (Located at)

Utility Attachments			
Telephone	North & South ditch.	Gas	
Power	3 wire OH North along fenceline.	Municipal	
Others		Problem (Y/N)	No
Remarks			

Approach Road / Embankment

	Last	Now	Explanation of Condition
Horizontal Alignment	8	8	Gradual grade to the West. 10mm transverse crack in ACP just East of pipe.
Vertical Alignment	7	7	
Roadway Width (m)	12.100		
Embankment	8	8	
Sideslope (__:1)	3.0		
(Height of Cover(m) : 0.8)			
Guardrail (Y/N)	No		
Approach Road / Embankment General Rating	7	7	

Upstream End

Culvert Component	Last	Now	Explanation of Condition
Direction	N		
End Treatment (Concrete, Steel, Others, None)	STEEL		
Headwall	X	X	
Collar	X	X	
Wingwalls	X	X	
(Shape :)			
Cutoff Wall	X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		7	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
Upstream End General Rating		7	7	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2700, Type: MP)				
Barrel Last Accessible Date	11-Mar-2010			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		8	N	(Unable to measure rise due to snow and ice in pipe. 11Mar2010).
Measured Rise (mm)	2690			
Measured At Ring No.	2			
Sag (mm)	10			
Percent Sag	0			
Sidewall		8	N	(Uncertain if measurement is accurate due to snow and ice in the pipe. 11Mar2010).
Measured Span (mm)	2692			
Measured At Ring No.				(At mid pipe. 11Mar2010).
Deflection (mm)	8			
Percent Deflection	0			(0.3%. 11Mar2010).
Floor		N	N	Under water.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		6	N	
Separation (mm)	25			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		7	7	Top half of pipe visible.
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2700, Type: MP)				
Fish Passage Adequacy		7	7	
Baffle		X	X	
(Type :)				
Waterway Adequacy		8	8	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		8	N	GR was 8 from 11Mar2010.
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		8	8	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		N	8	
Beavers (Y/N)	No			
Downstream End General Rating		7	7	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		8	8	Pasture field.
Bank Stability		8	8	
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading				Unknown.
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		8	8	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	88.9/55.6	Sufficiency Rating (Last/Now) (%)	85.0/67.0	Est. Repl. Yr	2055	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Jason Saly		Previous Assistant's Name				
Next Inspection Date	02-Aug-2013		Previous Inspection Date	11-Mar-2010			
Inspection Cycle (Default) (months)	21						
Comment							