

Bridge Culvert Inspection			
Bridge File Number	75205 -1 Bridge Culvert	Form Type	CUL1
Year Built	1986	Lot No.	4
Bridge or Town Name	LA CRETE	Inspector Name	Brian Pientsch
Located Over	TRIBUTARY TO PEACE RIVER, 8.10.30, WATERCRS-ST	Inspector Class	BR CLS A
Located On	697:02 C1 39.221	Assistant Name	Lisbeth Medina
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	19-Feb-2010
Legal Land Location	NE SEC 12 TWP 104 RGE 18 W5M	Data Entry By	Theresa Lacusta
Longitude, Latitude	-116:49:21, 58:01:12	Data Entry Date	08-Mar-2010
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Arnold Assenheimer
Contract Main. Area	CMA01	Review Date	08-Mar-2010
Clear Roadway/Skew	10 /	Dept. Reviewer Name	Steve Pasquan
AADT/Year	380 / 2008 (A)	Dept. Review Date	01-Apr-2010
Road Classification	RCU-210-110	Follow-Up By	
Detour Length (km)	18		

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	4300	SP	35.4	152X51	3.0	ROUND
Special Features								
Special Features Comment								

**Utilities (Located at)**

Utility Attachments			
Telephone		Gas	
Power		Municipal	
Others		Problem (Y/N)	
Remarks			

**Approach Road / Embankment**

	Last	Now	Explanation of Condition
Horizontal Alignment	7	7	Intersection 75m west.
Vertical Alignment	9	9	
Roadway Width (m)	10.000		
Embankment	7	6	
Sideslope ( __:1)	2.0		
(Height of Cover (m) : )			
Guardrail (Y/N)	No		
<b>Approach Road / Embankment General Rating</b>	<b>7</b>	<b>7</b>	

**Upstream End**

Culvert Component	Last	Now	Explanation of Condition
Direction			(South)
End Treatment (Concrete, Steel, Others, None)	CONCRETE		
Headwall	X	X	
Collar	N	N	Snow covered
Wingwalls	X	X	
(Shape : )			
Cutoff Wall	N	N	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		N	6	Ice and snow covered.
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)				
Scour Protection		N	N	No apparent scour problems.
(Type : )				
(Avg. Rock Size (mm) : )				
Scour/Erosion		N	N	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>8</b>	<b>6</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): -, Rise (mm): 4300, Type: SP)				
Barrel Last Accessible Date	19-Feb-2010			
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		7	7	(EST.-Mar 11, 2007)
Measured Rise (mm)				Floor covered with ice.
Measured At Ring No.				
Sag (mm)	0			
Percent Sag				
Sidewall		7	7	Deflection inward.
Measured Span (mm)	4297			
Measured At Ring No.	4			
Deflection (mm)	3			
Percent Deflection				
Floor		N	N	Ice cover
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		8	7	
Separation (mm)	0			
Longitudinal Seams		8	7	2N Stagger
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	Yes			
Coating		N	6	(SOME RUST ON BOTTOM & SIDE PLATES. NO CHANGE - 97/03/11)
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): -, Rise (mm): 4300, Type: SP)				
Ponding (Y/N)	No			
Fish Passage Adequacy		7	7	
Baffle		N	N	
(Type : )				
Waterway Adequacy		8	8	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>7</b>	<b>7</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction				(North)
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		N	N	
Bevel End		N	N	Ice & snow cover
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)				
Scour Protection		N	N	(Bevel projecting 2m from fill (photo). 2003/08/15)
(Type : )				
(Avg. Rock Size (mm) : )				
Scour/Erosion		N	N	Covered with snow.
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>4</b>	<b>4</b>	GR carried forward.
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel (U/S and D/S)</b>				
Alignment		6	6	
Bank Stability		6	6	Stable
HWM (m below Top of Culvert)				HWM not visible
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading				(Beaver cuttings-Nov 23, 2006)
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : <b>NONE</b> )				
(Fish Compensation Measure 2 : <b>NONE</b> )				
<b>Channel General Rating</b>		<b>6</b>	<b>6</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>77.8/77.8</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>77.2/75.0</b>	Est. Repl. Yr	2031	Maint. Req. (Y/N)	No
Special Comments for Next Inspection	Monitor d/s scour.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Brian Pientsch		Previous Assistant's Name	Tim Miskiman			
Next Inspection Date	19-May-2013		Previous Inspection Date	23-Nov-2006			
Inspection Cycle (Default) (months)	39						
Comment							