

Bridge Culvert Inspection			
Bridge File Number	76008 -2 Bridge Culvert	Form Type	CUL1
Year Built	2007	Lot No.	4
Bridge or Town Name	GROUARD	Inspector Name	Brian Pientsch
Located Over	TRIBUTARY TO WASH CREEK, 8.11.80.54.2.1, WATERCRS-ST	Inspector Class	BR CLS A
Located On	679:06 C1 14.394	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	09-Dec-2012
Legal Land Location	NE SEC 20 TWP 76 RGE 15 W5M	Data Entry By	Theresa Lacusta
Longitude, Latitude	-116:17:20, 55:36:06	Data Entry Date	09-Jan-2013
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Eric Carcoux
Contract Main. Area	CMA06	Review Date	08-Jan-2013
Clear Roadway/Skew	10.2 /	Dept. Reviewer Name	David Morrison
AADT/Year	120 / 2011 (A)	Dept. Review Date	28-Mar-2013
Road Classification		Follow-Up By	
Detour Length (km)			

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	2000	MP	33.24	125X26	2.8	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone	Temp line East fence.	Gas	
Power	OHP W side of row	Municipal	
Others		Problem (Y/N)	No
Remarks			

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment			8	
Vertical Alignment			8	
Roadway Width (m)	10.000			
Embankment			8	
Sideslope (__:1)	4.0			
(Height of Cover(m) : 1.9)				
Guardrail (Y/N)				
Approach Road / Embankment General Rating			8	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall			X	
Collar			X	
Wingwalls			X	
(Shape :)				
Cutoff Wall			X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End			8	
Heaving (mm)				
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	500			
Scour Protection			8	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion			8	
Beavers (Y/N)	No			
Upstream End General Rating			8	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1 , Primary Span, Location Code: MAIN , Span (mm): , Rise (mm): 2000 , Type: MP)				
Barrel Last Accessible Date	03-Dec-2012			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof			8	Ice on floor - no measurements
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)				
Percent Sag				
Sidewall			8	@ CL
Measured Span (mm)	1994			
Measured At Ring No.				
Deflection (mm)				
Percent Deflection				
Floor			N	Ice
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams			8	
Separation (mm)				
Longitudinal Seams			X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating			4	Black polymer coating peeling at ice level at every lockseam.-photo
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)				
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2000, Type: MP)				
Fish Passage Adequacy			7	
Baffle			X	
(Type :)				
Waterway Adequacy			8	
Icing (Y/N)	No			
Siltng (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating			8	

Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall			X	
Collar			X	
Wingwalls			X	
(Shape :)				
Cutoff Wall			X	
Bevel End			8	
Heaving (mm)				
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	500			
Scour Protection			8	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion			8	
Beavers (Y/N)	No			
Downstream End General Rating			8	

Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment			8	
Bank Stability			7	
HWM (m below Top of Culvert)				No HWM visible
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading				stable
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating			8	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	/88.9	Sufficiency Rating (Last/Now) (%)	/87.8	Est. Repl. Yr	2052	Maint. Req. (Y/N)	No
Special Comments for Next Inspection	Monitor asphaltic coating - peeling @ waterline.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name			Previous Assistant's Name				
Next Inspection Date	09-Mar-2016		Previous Inspection Date				
Inspection Cycle (Default) (months)	39						
Comment							