

Bridge Culvert Inspection			
Bridge File Number	76103 -2 Bridge Culvert	Form Type	CUL1
Year Built	2012	Lot No.	4
Bridge or Town Name	BLUEBERRY MT	Inspector Name	Russel Vanderschaaf
Located Over	BLUEBERRY CREEK, 8.10.83.1, WATERCRS-ST	Inspector Class	BR CLS B
Located On	680:02 C1 8.640	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	20-Mar-2012
Legal Land Location	SW SEC 17 TWP 80 RGE 7 W6M	Data Entry By	Lisa Fairhurst
Longitude, Latitude	-119:03:46, 55:55:38	Data Entry Date	27-Apr-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Eric Carcoux
Contract Main. Area	CMA05	Review Date	27-Mar-2012
Clear Roadway/Skew		Dept. Reviewer Name	David Morrison
AADT/Year	100 / 2011 (A)	Dept. Review Date	31-Oct-2012
Road Classification		Follow-Up By	
Detour Length (km)	3		

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	3990	SP	39.01	152X51	3.0	ROUND
Special Features								
Special Features Comment								

**Utilities (Located at)**

Utility Attachments			
Telephone		Gas	
Power		Municipal	
Others		Problem (Y/N)	No
Remarks			

**Approach Road / Embankment**

	Last	Now	Explanation of Condition
Horizontal Alignment		9	
Vertical Alignment		9	
Roadway Width (m)			
Embankment		4	Still under construction
Sideslope ( __:1)			
(Height of Cover(m) : )			
Guardrail (Y/N)			
<b>Approach Road / Embankment General Rating</b>		<b>9</b>	

**Upstream End**

Culvert Component	Last	Now	Explanation of Condition
Direction		W	
End Treatment (Concrete, Steel, Others, None)		CONCRETE	
Headwall		9	
Collar		9	
Wingwalls		9	
(Shape : )			
Cutoff Wall		9	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End			9	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)				
Scour Protection			9	
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>450</b> )				
Scour/Erosion			9	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>			<b>9</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : <b>1</b> , Primary Span, Location Code: <b>MAIN</b> , Span (mm): , Rise (mm): <b>3990</b> , Type: <b>SP</b> )				
Barrel Last Accessible Date	20-Mar-2012			
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof			N	Covered by ice
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)				
Percent Sag				
Sidewall			9	
Measured Span (mm)	3966			
Measured At Ring No.	6			
Deflection (mm)	34			
Percent Deflection	1			
Floor			N	Covered by ice
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams			9	
Separation (mm)	0			
Longitudinal Seams			9	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	Yes			
Coating			9	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 3990, Type: SP)				
Fish Passage Adequacy			9	
Baffle			X	
(Type : )				
Waterway Adequacy			9	
Icing (Y/N)	No			
Siltting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>			<b>9</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall			X	
Collar			X	
Wingwalls			X	
(Shape : )				
Cutoff Wall			X	
Bevel End			9	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)				
Scour Protection			9	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 450)				
Scour/Erosion			9	
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>			<b>9</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel (U/S and D/S)</b>				
Alignment			7	
Bank Stability			9	
HWM (m below Top of Culvert)				No HWM visible
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	NONE			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
<b>Channel General Rating</b>			<b>7</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>/100.0</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>/98.5</b>	Est. Repl. Yr	2065	Maint. Req. (Y/N)	No
Special Comments for Next Inspection	Construction to be completed Fall 2012		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name			Previous Assistant's Name				
Next Inspection Date	20-Jun-2015		Previous Inspection Date				
Inspection Cycle (Default) (months)	39						
Comment							