

| Bridge Culvert Inspection | | | |
|---------------------------|--|---------------------|---------------|
| Bridge File Number | 77747 -1 Bridge Culvert | Form Type | CUL1 |
| Year Built/Lined | 1957/2005 | Lot No. | 4 |
| Bridge or Town Name | INNISFAIL | Inspector Name | Owen Salava |
| Located Over | 3RD ORDER TRIBUTARY TO RED DEER RIVER, 3.85.2.1, WATERCRS-ST | Inspector Class | BR CLS A |
| Located On | 2:22 R1 22.185;2:22 L1 22.197 | Assistant Name | |
| Water Body Cl./Year | | Assistant Class | |
| Navigabil. Cl./Year | | Inspection Date | 13-Mar-2013 |
| Legal Land Location | SE SEC 7 TWP 35 RGE 28 W4M | Data Entry By | Marcia Chavez |
| Longitude, Latitude | -113:59:05, 51:59:13 | Data Entry Date | 27-Mar-2013 |
| Road Authority | Alberta Transportation (AIT) | Reviewer Name | John O'Brien |
| Contract Main. Area | CMA19 | Review Date | 17-Mar-2013 |
| Clear Roadway/Skew | 30.2 / 10 deg. (RHF) | Dept. Reviewer Name | Chris Black |
| AADT/Year | 28,800 / 2011 (A) | Dept. Review Date | 28-Mar-2013 |
| Road Classification | RFD-412.4-130 | Follow-Up By | |
| Detour Length (km) | 1 | | |

Bridge Culvert Information

| | | | | | | | | |
|--------------------------|-------------------|------|----------------|------|--------|---------------|--------------------|-------|
| Number of Culverts | 1 | | | | | | | |
| Pipe # | Barrel | Span | Rise (or Dia.) | Type | Length | Corr. Profile | Pl./Slab Thickness | Shape |
| 2 | MAIN FULL LINER | - | 1200 | MP | 91 | 125X26 | | ROUND |
| Special Features | STORM WATER DRAIN | | | | | | | |
| Special Features Comment | | | | | | | | |

Utilities (Located at)

| | | | |
|---------------------|-----------|---------------|----|
| Utility Attachments | | | |
| Telephone | West r/w. | Gas | |
| Power | | Municipal | |
| Others | | Problem (Y/N) | No |
| Remarks | | | |

Approach Road / Embankment

| | | Last | Now | Explanation of Condition |
|--|--------|----------|----------|--------------------------|
| Horizontal Alignment | | 9 | 9 | |
| Vertical Alignment | | 8 | 8 | |
| Roadway Width (m) | 29.000 | | | |
| Embankment | | 7 | 7 | |
| Sideslope (_ :1) | 7.0 | | | |
| (Height of Cover(m) : 7) | | | | |
| Guardrail (Y/N) | No | | | |
| Approach Road / Embankment General Rating | | 8 | 8 | |

Upstream End

| Culvert Component | | Last | Now | Explanation of Condition |
|---|-------|------|-----|--------------------------|
| Direction | | E | | |
| End Treatment (Concrete, Steel, Others, None) | STEEL | | | |
| Headwall | | X | X | |
| Collar | | X | X | |
| Wingwalls | | X | X | |
| (Shape :) | | | | |
| Cutoff Wall | | X | X | |

| Upstream End | | | | |
|---|-------|----------|----------|---|
| Culvert Component | | Last | Now | Explanation of Condition |
| Bevel End | | 7 | 7 | |
| Heaving (mm) | 0 | | | |
| Invert Above/Below Stream Bed | BELOW | | | |
| Above/Below (mm) | 100 | | | |
| Scour Protection | | 7 | N | Snow covered. |
| (Type : RIP RAP) | | | | |
| (Avg. Rock Size(mm) : 300) | | | | |
| Scour/Erosion | | 7 | N | |
| Beavers (Y/N) | No | | | |
| Upstream End General Rating | | 7 | 7 | |
| Bridge Culvert Barrel | | | | |
| Culvert Component | | Last | Now | Explanation of Condition |
| (Pipe # : 2 , Primary Span, Location Code: MAIN , Span (mm): , Rise (mm): 1200 , Type: MP) | | | | |
| Barrel Last Accessible Date | | | | Not bridge-sized; over 1/2 full of ice. Viewed from ends, looks good. |
| Special Features | | | | |
| Special Feature | | N | N | |
| (Type : STORM WATER DRAIN) | | | | |
| Special Feature | | | | |
| (Type :) | | | | |
| Roof | | N | N | |
| Measured Rise (mm) | | | | |
| Measured At Ring No. | | | | |
| Sag (mm) | | | | |
| Percent Sag | | | | |
| Sidewall | | N | N | |
| Measured Span (mm) | | | | |
| Measured At Ring No. | | | | |
| Deflection (mm) | | | | |
| Percent Deflection | | | | |
| Floor | | N | N | |
| Bulge (mm) | | | | |
| Measured At Ring No. | | | | |
| Abrasion (Y/N) | | | | |
| Circumferential Seams | | N | N | |
| Separation (mm) | | | | |
| Longitudinal Seams | | X | X | |
| Total No. of Cracked Rings | | | | |
| Total No. of Rings with Two Cracked Seams | | | | |
| Min. Remaining Steel Between Cracks (mm) | | | | |
| Proper Lap (Y/N) | | | | |
| Longitudinal Stagger (Y/N) | | | | |
| Coating | | 7 | 7 | |
| Corrosion By Soil (Y/N) | | | | |
| Corrosion By Water (Y/N) | | | | |
| Camber POS/ZERO/NEG | | | | |
| Ponding (Y/N) | Yes | | | |

| Bridge Culvert Barrel | | | | |
|---|-------|----------|----------|--|
| Culvert Component | | Last | Now | Explanation of Condition |
| (Pipe # : 2, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1200, Type: MP) | | | | |
| Fish Passage Adequacy | | X | X | |
| Baffle | | N | N | |
| (Type :) | | | | |
| Waterway Adequacy | | 6 | 6 | |
| Icing (Y/N) | | | | |
| Silting (Y/N) | | | | |
| Drift (Y/N) | | | | |
| Barrel General Rating | | N | N | |
| Downstream End | | | | |
| Culvert Component | | Last | Now | Explanation of Condition |
| Direction | | W | | |
| End Treatment (Concrete, Steel, Others, None) | STEEL | | | |
| Headwall | | X | X | |
| Collar | | X | X | |
| Wingwalls | | X | X | |
| (Shape :) | | | | |
| Cutoff Wall | | X | X | |
| Bevel End | | 7 | 7 | |
| Heaving (mm) | 0 | | | |
| Invert Above/Below Stream Bed | BELOW | | | |
| Above/Below (mm) | 100 | | | |
| Scour Protection | | 7 | N | Snow covered. |
| (Type : RIP RAP) | | | | |
| (Avg. Rock Size(mm) : 300) | | | | |
| Scour/Erosion | | 7 | N | Snow covered. |
| Beavers (Y/N) | No | | | |
| Downstream End General Rating | | 7 | 7 | |
| Structure Usage | | | | |
| | | Last | Now | Explanation of Condition |
| Channel (U/S and D/S) | | | | |
| Alignment | | 5 | 5 | Channel takes 90 degree turn @ outlet. |
| Bank Stability | | 7 | 7 | |
| HWM (m below Top of Culvert) | | | | HWM not visible. |
| Drift (Y/N) | No | | | |
| Channel Bottom Degrading/Aggrading | | | | Unknown. |
| Beavers (Y/N) | No | | | |
| (Fish Compensation Measure 1 : NONE) | | | | |
| (Fish Compensation Measure 2 : NONE) | | | | |
| Channel General Rating | | 5 | 5 | |

| Maintenance Recommendations | | | | | | | |
|---|--|--|---------------------------|---------------|-----------|-------------------|----|
| Inspector Recommendations | Year | Inspector Comments | Department Comments | Target Year | Est. Cost | Cat # | |
| SHOTCRETE REPAIRS | | | | | | | |
| PLACE ADDITIONAL RIP RAP | | | | | | | |
| REMOVE DRIFT ACCUMULATION | | | | | | | |
| INSTALL CONCRETE/STEEL LINING | | | | | | | |
| INSTALL STRUTS | | | | | | | |
| INSTALL CONCRETE COLLAR/CUTOFF | | | | | | | |
| REPAIR SEAMS | | | | | | | |
| OTHER ACTION | | | | | | | |
| OTHER ACTION | | | | | | | |
| OTHER ACTION | | | | | | | |
| OTHER ACTION | | | | | | | |
| Structural Condition Rating (Last/Now) (%) | 55.6/55.6 | Sufficiency Rating (Last/Now) (%) | 59.3/59.2 | Est. Repl. Yr | 2040 | Maint. Req. (Y/N) | No |
| Special Comments for Next Inspection | Service road outlet provides good access without disruption to HWY 2 traffic. Remove from active inspection list; not bridge-sized, limited access, single pipe. | | Department Comments | | | | |
| Maintenance Reviewed By | | | Date | | | Estimated Total | 0 |
| Proposed Long-Term Strategy | | | | | | | |
| On 3-Year Program (Y/N) | | | | | | | |
| Proposed Action | | | | | | | |
| Previous Inspector's Name | Owen Salava | | Previous Assistant's Name | | | | |
| Next Inspection Date | 13-Dec-2014 | | Previous Inspection Date | 11-Aug-2011 | | | |
| Inspection Cycle (Default) (months) | 21 | | | | | | |
| Comment | | | | | | | |