

Bridge Culvert Inspection				
Bridge File Number	79996 -1 Bridge Culvert		Form Type	CUL1
Year Built	1996		Lot No.	4
Bridge or Town Name	INDUS		Inspector Name	Garry Roberts
Located Over	IRRIGATION C, WATERCRS-IC		Inspector Class	BR CLS A
Located On	901:48 C1 3.028		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	06-Jan-2012
Legal Land Location	NE SEC 26 TWP 22 RGE 26 W4M		Data Entry By	Anne Roberts
Longitude, Latitude	-113:29:37, 50:54:25		Data Entry Date	05-Feb-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Tom Carey
Contract Main. Area	CMA30		Review Date	18-Jan-2012
Clear Roadway/Skew	12.8 / 20 deg. (RHF)		Dept. Reviewer Name	Tim Davies
AADT/Year	2,800 / 2010 (A)		Dept. Review Date	06-Feb-2012
Road Classification	RAU-213.4-120		Follow-Up By	
Detour Length (km)	3			

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	1600	MP	44	125X26	2.8	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)				
Utility Attachments				
Telephone	North ROW		Gas	HP gas line d/s 30m S of CL
Power	East		Municipal	
Others	75mm dia plastic drain line into u/s bevel		Problem (Y/N)	No
Remarks				

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		8	9	
Vertical Alignment		8	8	
Roadway Width (m)	12.800			
Embankment		8	8	
Sideslope ( _ :1)	5.0			
(Height of Cover(m) : 2)				
Guardrail (Y/N)	Yes			
<b>Approach Road / Embankment General Rating</b>		<b>8</b>	<b>8</b>	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		8	7	
Heaving (mm)	50			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		8	8	
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>200</b> )				
Scour/Erosion		8	8	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>8</b>	<b>7</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : <b>1</b> , Primary Span, Location Code: <b>MAIN</b> , Span (mm): , Rise (mm): <b>1600</b> , Type: <b>MP</b> )				
Barrel Last Accessible Date	06-Jan-2012			
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		8	8	
Measured Rise (mm)	1570			
Measured At Ring No.	3			
Sag (mm)	30			
Percent Sag	1			
Sidewall		8	8	
Measured Span (mm)	1630			
Measured At Ring No.	3			
Deflection (mm)	30			
Percent Deflection	1			
Floor		N	7	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		8	8	
Separation (mm)	20			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		6	6	Mild corrosion @ water level
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	Yes			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1600, Type: MP)				
Fish Passage Adequacy		X	7	
Baffle		X	X	
(Type : )				
Waterway Adequacy		6	6	Waterline above mid sidewall
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>8</b>	<b>8</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		
End Treatment (Concrete, Steel, Others, None)		STEEL		
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		8	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed		BELOW		
Above/Below (mm)	300			
Scour Protection		8	8	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 200)				
Scour/Erosion		8	8	
Beavers (Y/N)		No		
<b>Downstream End General Rating</b>		<b>8</b>	<b>7</b>	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		6	6	Bends 90 deg @ north & follows road
Bank Stability		8	8	
HWM (m below Top of Culvert)		0.7		No visible HWM
Drift (Y/N)		No		
Channel Bottom Degrading/Aggrading		AGGRADING		
Beavers (Y/N)		No		
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
<b>Channel General Rating</b>		<b>6</b>	<b>6</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>88.9/88.9</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>78.8/76.6</b>	Est. Repl. Yr	2048	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Jason Rusu		Previous Assistant's Name				
Next Inspection Date	06-Apr-2015		Previous Inspection Date	15-Oct-2008			
Inspection Cycle (Default) (months)	39						
Comment							