

Bridge Culvert Inspection				
Bridge File Number	80650 -1 Bridge Culvert		Form Type	CUL1
Year Built	1983		Lot No.	4
Bridge or Town Name	LAKE ISLE		Inspector Name	Kris Bosters
Located Over	TRAIL-ANIMAL, OVER SP		Inspector Class	BR CLS A
Located On	633:02 C1 7.940		Assistant Name	Brian Cote
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	20-Jul-2012
Legal Land Location	SW SEC 1 TWP 54 RGE 6 W5M		Data Entry By	Theresa Lacusta
Longitude, Latitude	-114:45:47, 53:37:51		Data Entry Date	20-Aug-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Eric Carcoux
Contract Main. Area	CMA12		Review Date	19-Aug-2012
Clear Roadway/Skew	10 /		Dept. Reviewer Name	Brent Herrick
AADT/Year	440 / 2011 (A)		Dept. Review Date	22-Aug-2012
Road Classification	RCU-209-110		Follow-Up By	
Detour Length (km)	20			

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	2200	MP	29	125X26	2.8	ROUND
Special Features								
Special Features Comment								

Posting Information												
Required Vert. Clearance Posting (m)												
Posted Vertical Clearance (Y/N)			No									
Posted:	Lane	EB	On Bridge (m)		In Advance (Y/N)	No	Lane	WB	On Bridge (m)		In Advance (Y/N)	No
Remarks												

Utilities (Located at)			
Utility Attachments			
Telephone	South r/w.		Gas
Power	2 wires 19 m south c/l.		Municipal
Others			Problem (Y/N) No
Remarks	File tag U/S, North.		

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	Farm entrances to East and field.
Vertical Alignment		7	7	
Roadway Width (m)	10.000			
Embankment		N	7	
Sideslope (___:1)	3.0			
(Height of Cover(m) : 0.8)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		7	7	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		
End Treatment (Concrete, Steel, Others, None)		NONE		
Headwall		X	X	
Collar		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Wingwalls (Shape :)		X	X	
Cutoff Wall		X	X	
Bevel End		X	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection (Type :) (Avg. Rock Size(mm) :)		N	7	
Scour/Erosion		N	7	
Beavers (Y/N)	No			
Upstream End General Rating		8	7	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2200, Type: MP)				
Barrel Last Accessible Date	20-Jul-2012			
Special Features				
Special Feature (Type :)				
Special Feature (Type :)				
Roof		N	7	Minor dents @ both ends, no problem. Dirt on floor. Could not measure. Roof appears to be in good condition. Estimated 2100 @ R2 from North.
Measured Rise (mm)				
Measured At Ring No.	2			
Sag (mm)				
Percent Sag	5			
Sidewall		7	7	
Measured Span (mm)	2275			
Measured At Ring No.	2			
Deflection (mm)	75			
Percent Deflection	3			
Floor		N	N	Covered with mud.
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		5	5	
Separation (mm)	30			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		7	7	Minor superficial rust.
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2200, Type: MP)				
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type :)				
Waterway Adequacy		X	X	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		7	7	

Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		X	X	
Heaving (mm)				
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	100			
Scour Protection		X	7	
(Type :)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		X	7	
Beavers (Y/N)	No			
Downstream End General Rating		7	7	

Structure Usage				
		Last	Now	Explanation of Condition
Grade Separation				
Road Alignment		7	7	Mud
Roadway Surface		6	6	
(Type :)				
Icing (Y/N)	No			
Traffic Safety Features		X	X	
Type				
Lighting		X	X	
Barrel Leakage (Y/N)	No			

Structure Usage				
		Last	Now	Explanation of Condition
Drainage		5	5	
Structure In Use (Y/N)	Yes			
Grade Separation General Rating		5	5	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	77.8/77.8	Sufficiency Rating (Last/Now) (%)	81.9/80.8	Est. Repl. Yr	2032	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Jacob Oresile		Previous Assistant's Name				
Next Inspection Date	20-Oct-2015		Previous Inspection Date	02-Feb-2009			
Inspection Cycle (Default) (months)	39						
Comment							