

Bridge Culvert Inspection				
Bridge File Number	81733 -1 Bridge Culvert		Form Type	CULM
Year Built	1991		Lot No.	4
Bridge or Town Name			Inspector Name	Russel Vanderschaaf
Located Over	WATERCOURSE, WATERCRS-NI		Inspector Class	BR CLS B
Located On	717:02 C1 22.784		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	26-Aug-2012
Legal Land Location	SW SEC 22 TWP 84 RGE 12 W6M		Data Entry By	Theresa Lacusta
Longitude, Latitude	-119:49:11, 56:17:36		Data Entry Date	25-Sep-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Eric Carcoux
Contract Main. Area	CMA04		Review Date	24-Sep-2012
Clear Roadway/Skew	10.1 / 5 deg. (RHF)		Dept. Reviewer Name	Steve Pasquan
AADT/Year	160 / 2011 (A)		Dept. Review Date	07-Jan-2013
Road Classification	RCU-209G-90		Follow-Up By	
Detour Length (km)	3			

Bridge Culvert Information								
Number of Culverts		2						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	1200	MP	35	65X13	2.8	ROUND
2	MAIN	-	1200	MP	35	65X13	2.8	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)			
Utility Attachments			
Telephone	West r/w 15m from c/l.		Gas
Power	1 wire East r/w 15m from c/l.		Municipal
Others			Problem (Y/N) No
Remarks			

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	Slight crest curve to South.
Vertical Alignment		7	7	
Roadway Width (m)	10.100			
Embankment		8	8	
Sideslope (__:1)	5.0			
(Height of Cover(m) : 2)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		7	7	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type:)				
Direction		W		South pipe. Water 0.7 + 0.8m from crowns.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type:)				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection		4	4	1.5 long x 0.5 wide x 0.5m deep scour along South side of bevel.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 200)				
Scour/Erosion		4	4	Scour along South side of bevel.
Beavers (Y/N)	No			
Upstream End General Rating		4	4	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1200, Type: MP)				
Barrel Last Accessible Date				Too much water & silt to enter barrel.
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		3	3	Viewed from ends. Barrel appears to have excessive deflections near c/l with flattening of the roof.
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)				
Percent Sag				
Sidewall		3	3	Viewed from ends. Deflection appears to be in the 10-15% range.
Measured Span (mm)				
Measured At Ring No.				
Deflection (mm)				
Percent Deflection				
Floor		N	N	Too much silt & water to view.
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		N	N	
Separation (mm)				
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		N	X	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1200, Type: MP)				
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	Yes			About 200mm at D/S end.
Fish Passage Adequacy		5	5	
Baffle		X	X	
(Type :)				
Waterway Adequacy		4	4	Pipes flows full.
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		3	3	

Bridge Culvert Barrel					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1200, Type: MP)					
Barrel Last Accessible Date				Too much silt & water to enter.	
Special Features					
Special Feature					
(Type :)					
Special Feature					
(Type :)					
Roof		3	3	Viewed from ends. Barrel appears to have excessive deflections with flattening of the roof near c/l.	
Measured Rise (mm)					
Measured At Ring No.					
Sag (mm)					
Percent Sag					
Sidewall		3	3	Viewed from ends. Deflections appear to be in the 10-15% range.	
Measured Span (mm)					
Measured At Ring No.					
Deflection (mm)					
Percent Deflection					
Floor		N	N	Too much silt & water to view.	
Bulge (mm)					
Measured At Ring No.					
Abrasion (Y/N)					
Circumferential Seams		N	N		
Separation (mm)					
Longitudinal Seams		X	X		
Total No. of Cracked Rings					
Total No. of Rings with Two Cracked Seams					
Min. Remaining Steel Between Cracks (mm)					
Proper Lap (Y/N)					
Longitudinal Stagger (Y/N)					
Coating		N	N		
Corrosion By Soil (Y/N)					
Corrosion By Water (Y/N)					

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1200, Type: MP)				
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	Yes			About 200mm at D/S end.
Fish Passage Adequacy		5	5	
Baffle		X	X	
(Type :)				
Waterway Adequacy		4	4	Pipe flows full.
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		3	3	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type:)				
Direction		E		Water 0.5m from crowns
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		7	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 200)				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
Downstream End General Rating		7	7	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		6	6	Makes 90 degree bend U/S.
Bank Stability		7	7	
HWM (m below Top of Culvert)	0.1			Staining near crown at U/S end. Would flow full at c/l.
Drift (Y/N)	Yes			Beaver cuttings & deadfall.
Channel Bottom Degrading/Aggrading	NONE			Heavy beaver activity D/S.
Beavers (Y/N)	Yes			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				

Structure Usage				
		Last	Now	Explanation of Condition
Channel General Rating		6	6	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	33.3/33.3	Sufficiency Rating (Last/Now) (%)	44.9/44.9	Est. Repl. Yr	2021	Maint. Req. (Y/N)	No
Special Comments for Next Inspection	Assessment completed in 2009. Monitor barrel shape.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Kris Bosters		Previous Assistant's Name				
Next Inspection Date	26-Nov-2015		Previous Inspection Date	28-Jul-2009			
Inspection Cycle (Default) (months)	39						
Comment							