

Bridge Culvert Inspection			
Bridge File Number	81877 -1 Bridge Culvert	Form Type	CUL1
Year Built	1994	Lot No.	4
Bridge or Town Name	MOUNTAIN VIE	Inspector Name	Jason Rusu
Located Over	TRIBUTARY TO CROOKED CREEK, 2.12.22.5.18.1, WATERCRS-ST	Inspector Class	BR CLS A
Located On	5:02 C1 1.810	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	28-Oct-2011
Legal Land Location	SE SEC 22 TWP 2 RGE 29 W4M	Data Entry By	Alyssa Boynton
Longitude, Latitude	-113:47:16, 49:08:19	Data Entry Date	21-Nov-2011
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Garry Roberts
Contract Main. Area	CMA25	Review Date	09-Nov-2011
Clear Roadway/Skew	13 / 10 deg. (RHF)	Dept. Reviewer Name	Tim Davies
AADT/Year	710 / 2010 (A)	Dept. Review Date	25-Nov-2011
Road Classification	RAU-211.8-110	Follow-Up By	
Detour Length (km)	42		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	2700	MP	34	125X26	2.8	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone	@ SOUTH R/W	Gas	
Power	3 W 100 m NORTH & 1 W CROSSES	Municipal	
Others	ROAD 100 m E & W	Problem (Y/N)	No
Remarks			

Approach Road / Embankment

	Last	Now	Explanation of Condition
Horizontal Alignment	6	6	IN CURVE-SUPERELEVATED
Vertical Alignment	7	7	
Roadway Width (m)	12.000		
Embankment	7	7	
Sideslope (__:1)	5.0		
(Height of Cover(m) : 1)			
Guardrail (Y/N)	No		
Approach Road / Embankment General Rating	6	6	

Upstream End

Culvert Component	Last	Now	Explanation of Condition
Direction	N		NORTH
End Treatment (Concrete, Steel, Others, None)	STEEL		
Headwall	X	X	
Collar	X	X	
Wingwalls	X	X	
(Shape :)			
Cutoff Wall	X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	500			
Scour Protection		7	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 400)				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
Upstream End General Rating		7	7	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2700, Type: MP)				
Barrel Last Accessible Date	28-Oct-2011			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		8	8	est
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)	33			
Percent Sag	1			
Sidewall		8	8	
Measured Span (mm)	2733			
Measured At Ring No.	3			
Deflection (mm)	33			
Percent Deflection	1			
Floor		N	N	400mm water 100mm silt
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		8	8	
Separation (mm)	30			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		6	6	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2700, Type: MP)				
Fish Passage Adequacy		7	7	
Baffle		X	X	
(Type :)				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		8	8	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		SOUTH
End Treatment (Concrete, Steel, Others, None)		STEEL		
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	100			
Invert Above/Below Stream Bed		BELOW		
Above/Below (mm)	200			
Scour Protection		7	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 350)				
Scour/Erosion		7	7	
Beavers (Y/N)		No		
Downstream End General Rating		7	7	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		6	6	MEANDERS @ NORTH
Bank Stability		6	6	
HWM (m below Top of Culvert)	2.0			
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading		DEGRADING		
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		6	6	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	88.9/88.9	Sufficiency Rating (Last/Now) (%)	79.8/79.8	Est. Repl. Yr	2033	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name				
Next Inspection Date	28-Jul-2013		Previous Inspection Date	18-Oct-2009			
Inspection Cycle (Default) (months)	21						
Comment							