

Bridge Culvert Inspection			
Bridge File Number	86094 -2 Bridge Culvert	Form Type	CUL1
Year Built	2011	Lot No.	4
Bridge or Town Name		Inspector Name	Brian Pientsch
Located Over	WATERCOURSE, WATERCRS-NI	Inspector Class	BR CLS A
Located On	58:06 C1 37.938	Assistant Name	Clem Guenette
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	11-Jan-2012
Legal Land Location	SW SEC 24 TWP 110 RGE 23 W5M	Data Entry By	Theresa Lacusta
Longitude, Latitude	-117:41:53, 58:33:44	Data Entry Date	04-Mar-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Eric Carcoux
Contract Main. Area	CMA01	Review Date	26-Feb-2012
Clear Roadway/Skew	15 / 0 deg.	Dept. Reviewer Name	David Morrison
AADT/Year	730 / 2011 (A)	Dept. Review Date	30-Mar-2012
Road Classification	RAU-211.8-110	Follow-Up By	
Detour Length (km)	999		

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	-	1800	MP	35	125X26	2.8	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)			
Utility Attachments			
Telephone		Gas	
Power	4 wire o/h, 50m South	Municipal	
Others		Problem (Y/N)	No
Remarks			

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment			9	
Vertical Alignment			8	
Roadway Width (m)	15.000			
Embankment			8	
Sideslope (_ :1)				
(Height of Cover(m) : 1)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating			8	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall			X	
Collar			X	
Wingwalls			X	
(Shape :)				
Cutoff Wall			X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End			9	
Heaving (mm)				
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection			N	Mostly snow covered.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion			N	Snow covered.
Beavers (Y/N)	No			
Upstream End General Rating			9	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1800, Type: MP)				
Barrel Last Accessible Date	11-Jan-2012			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof			9	
Measured Rise (mm)	1820			@ CL
Measured At Ring No.				Deflection upward
Sag (mm)	20			
Percent Sag	1			
Sidewall			9	
Measured Span (mm)	1800			@ CL
Measured At Ring No.				
Deflection (mm)				
Percent Deflection				
Floor			9	
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams			9	
Separation (mm)	25			
Longitudinal Seams			X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating			9	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1800, Type: MP)				
Fish Passage Adequacy			8	
Baffle			X	
(Type :)				
Waterway Adequacy			9	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating			9	

Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall			X	
Collar			X	
Wingwalls			X	
(Shape :)				
Cutoff Wall			X	
Bevel End			N	Snow covered
Heaving (mm)				
Invert Above/Below Stream Bed				
Above/Below (mm)				
Scour Protection			N	Snow covered
(Type :)				
(Avg. Rock Size(mm) :)				
Scour/Erosion			N	SNow covered.
Beavers (Y/N)	No			
Downstream End General Rating			N	

Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment			6	Channel turns 45deg. to enter culvert.
Bank Stability			8	
HWM (m below Top of Culvert)				HWM not visible
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	NONE			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating			6	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	/100.0	Sufficiency Rating (Last/Now) (%)	/93.3	Est. Repl. Yr	2061	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name			Previous Assistant's Name				
Next Inspection Date	11-Oct-2013		Previous Inspection Date				
Inspection Cycle (Default) (months)	21						
Comment							