

Bridge Culvert Inspection				
Bridge File Number	00958 -1 Bridge Culvert		Form Type	CUL1
Year Built	1970		Lot No.	4
Bridge or Town Name	IRVINE		Inspector Name	Tom Carey
Located Over	ROSS CREEK, 2.7, WATERCRS-ST		Inspector Class	BR CLS A
Located On	515:02 C1 4.957		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	13-Mar-2012
Legal Land Location	SW SEC 6 TWP 10 RGE 2 W4M		Data Entry By	Erin Roberts
Longitude, Latitude	-110:16:29, 49:47:10		Data Entry Date	08-Apr-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Garry Roberts
Contract Main. Area	CMA23		Review Date	25-Mar-2012
Clear Roadway/Skew	11.4 / 10 deg. (RHF)		Dept. Reviewer Name	Tim Davies
AADT/Year	80 / 2011 (A)		Dept. Review Date	17-Apr-2012
Road Classification	RCU-209-110		Follow-Up By	
Detour Length (km)	5			

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	3475	3840	SPE	43.7	152X51	4.2,4.2,4.2	ELLIPSE
Special Features								
Special Features Comment								

**Utilities (Located at)**

Utility Attachments			
Telephone	South side.	Gas	
Power	1 wire crossing road 40m West, North side.	Municipal	
Others		Problem (Y/N)	No
Remarks			

**Approach Road / Embankment**

	Last	Now	Explanation of Condition
Horizontal Alignment	7	7	Farm entrance 30m East. Bottom of coulee, 300m sight distance.
Vertical Alignment	5	5	
Roadway Width (m)	11.400		
Embankment	N	7	
Sideslope ( _ :1)	3.0		
(Height of Cover(m) : <b>3.8</b> )			
Guardrail (Y/N)	No		
<b>Approach Road / Embankment General Rating</b>	<b>5</b>	<b>5</b>	

**Upstream End**

Culvert Component	Last	Now	Explanation of Condition
Direction	S		South
End Treatment (Concrete, Steel, Others, None)	CONCRETE		
Headwall	X	X	
Collar	5	5	Slope concrete slab on East side cracked and broken.
Wingwalls	X	X	
(Shape : )			
Cutoff Wall	N	N	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			snow covered
Above/Below (mm)	700			
Scour Protection		N	7	
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>500</b> )				
Scour/Erosion		N	7	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>5</b>	<b>5</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 3475, Rise (mm): 3840, Type: SPE)				
Barrel Last Accessible Date	13-Mar-2012			
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		5	5	Estimate
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)	250			
Percent Sag	6			
Sidewall		5	5	
Measured Span (mm)	3665			
Measured At Ring No.	5			
Deflection (mm)	190			
Percent Deflection	5			
Floor		N	N	Ice and water covered.
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		7	7	
Separation (mm)	0			
Longitudinal Seams		7	7	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	No			
Coating		6	6	Bolts have white stains and corrosion stains.
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 3475, Rise (mm): 3840, Type: SPE)				
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type : )				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>5</b>	<b>5</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		North
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		7	8	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	1000			
Scour Protection		N	8	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 800)				
Scour/Erosion		N	8	
Beavers (Y/N)	No			New class 2 rip rap seen at bevel and sides of stream.
<b>Downstream End General Rating</b>		<b>4</b>	<b>8</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel (U/S and D/S)</b>				
Alignment		8	7	
Bank Stability		N	7	
HWM (m below Top of Culvert)				HWM not visible
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading				
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
<b>Channel General Rating</b>		<b>8</b>	<b>7</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>55.6/55.6</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>63.7/67.1</b>	Est. Repl. Yr	2022	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Tim Davies		Previous Assistant's Name				
Next Inspection Date	13-Jun-2015		Previous Inspection Date	12-Mar-2009			
Inspection Cycle (Default) (months)	39						
Comment							