



Photo 1

Looking south away from Hwy 2:50 junction

- Drift Pile River running north (on left of photo) (on east side) beside local road
- On left (east) side, top of eroded bank at about 7m setback to edge of local road
- On right (west) side, edge of local road is offset about 14m from a dugout pond



Photo 2

Looking south upstream from top of setback

- A meander scour bank is being eroded to encroach towards the roadway
- Roadway on right side of photo

Note: Photos taken on July 17, 2008



Photo 3
Looking north towards junction Hwy 2:50
- Drift-Pile River on east side (right of photo)
- Dugout pond on west side (left of photo)