BF 79332 Local Road Over Henderson Ck Tributary
Hydrotechnical Summary

Channel Capacity :

S = 0.004
B = 2 m, h = 1.2 m, T_h = 4 m
Use n = 0.05

At Bank Height : Y = 1.2 m, V = 1.0 m/s, Q = 4 cms
At Channel Capacity : Y = 1.8 m, V = 1.5 m/s, Q = 10 cms

Historical Highwater Data :

There are no direct HW observations at this site. A 1979 report estimates Q = 8cms. A 1997 photo shows a scour hole d/s with some slumping of the adjacent fill.

There are no WSC gauges on this stream. Nearby gauges suggest June 1990 as the largest event recorded, with other HW events noted in April of 1974 and 1997. There are no storms in the database that exceed 100mm in rainfall for this area.

Basin Runoff Potential :

d = 70 mm, T_p = 20 hrs, q = 1.0 cms/km^2.
Gross DA = 14 km^2.
Q_p = 14 cms.

Conclusion :

The channel capacity estimate is consistent with historic observations and within the basin runoff potential.

Recommended parameters : Y = 1.8 m, V = 1.5 m/s, Q = 10 cms.