



Photo 1 – 2005

General view of the Barrier Bluffs site from the 2005 inspection, illustrating the relative position of the slope (potential rockfall source area) and Highway 40.



Photo 2 (top) – June 2009

Ditch along the toe of the unvegetated colluvium slope. Note the large boulders that have rolled slightly beyond the toe of the cut slope. However, no new boulders were evident in comparison to the photos from the 2005 inspection.



Photo 3 (bottom) – June 2009

Closer view of the toe of the colluvium slope, as seen from the edge of the highway.