



Photo 1 – Looking northeast at catch basin cracks (May 17, 2011).



Photo 2 – Looking southwest at catch basin cracks (May 17, 2011).



Photo 3 – Looking northeast at west crack (May 17, 2011).



Photo 4 – Looking northeast at east crack (May 17, 2011).



Photo 5 – Looking east along north guardrail (May 17, 2011).



Photo 6 – Looking northeast at culvert dip at Station 1+850 (May 17, 2011).



Photo 7 – Gentle dip and pavement crack at Station 1+850 (May 17, 2011).



Photo 8 – Looking west at cracks above bin wall. Note tilt of SI30 casing just beyond guardrail (May 17, 2011).



Photo 9 – Looking west at bin wall (Station 1+200) (May 17, 2011).



Photo 10 – Looking east at bin wall (Station 1+200) (May 17, 2011).