



Photo #1 Looking at the highway surface at the slide area. The fresh patch defines the headscarp of the slide along the EBL(looking west)



Photo #2 Looking east at an open headscarp crack in the highway EBL



Photo #3 Looking north at an open longitudinal crack on the highway EBL; note the drop across the crack and the depression along the EBL



Photo #4 Looking west at the highway south side slope; note the sharp drop on the edge of the road



Photo #5 Looking at the south muskeg ditch; note the hump around the ditch, the titling branches and the debris falling into the ditch



Photo #6 Looking at the terrain to the south of the fence; note the titling of the fence posts and the hummocky nature of the ground, looking west