



Photo #1 Looking east at the highway surface. A new ACP patch was placed in fall 2012



Photo #2 Looking east from the western flank of the landslide at a reflective diagonal crack in the highway EBL



Photo #3 Looking east from the middle of the landslide at longitudinal reflective crack in the highway EBL



Photo #4 Looking at voids formed at a few locations along the tops of the piles