



**Photo 1:** Judah Hill Slide #1, Zone D2, cracks in pavement, May 2003



**Photo 2:** Judah Hill, scarp of debris flow has retrogressed, location of new slide



**Photo 3:** Judah Hill New Slide, cracks in shoulder, pavement patched, May 2003



**Photo 4:** Judah Hill New Slide, scarp, pavement patched, May 2003



**Photo 5:** Judah Hill Zone B1, settlement and cracks in pavement, stone columns pushing through, May 2003



**Photo 6:** Judah Hill Zone B1, settlement and cracks in pavement, stone columns pushing through, May 2003



**Photo 7:** Judah Hill, Slide at Railway Crossing, erosion of buttress, April 2003