



Photo 1 – Slide No 2 – note the barrier has been moved to the edge of the pavement from its previous location just left of the ditch invert. Note the cable dangling across the failure. June 15, 2005