

Lookout Slides (57+500)



Photo 5.
Looking north towards the car park area at the Lookout. Note the jog in the guardrail where the slide is encroaching on the paved area.



Photo 6.
Several slides on the steep slope below the Lookout area. The average slope angle is 38° . The slide area in the foreground is approximately 30 m wide and is currently encroaching on the car park.



Photo 7.
Slide runout below the Lookout. The slide debris has the appearance of a flow, suggesting that water plays a part in debris mobility.



Photo 8.
Slide just beyond / to the north of the Lookout. The slide is about 26 m wide, and within 4 m of the guardrail. This is the origin of the slide runout debris in Photo 7.



Photo 9.
Minor cracking in the
pavement at the slide
backscarp north of
the Lookout.