



Photo 1 - Looking east at sinkhole overtop culvert alignment. Note extended cracks on south side, June 15, 2006.





Photo 2a - Looking east across site at severe, fresh slumping. Note dropped slide block, June 15, 2006.



Photo 2b - Looking south across gabion outlet at severe, fresh slumping along site boundary edge, June 15, 2006.





Photo 3 - Looking at culvert outlet, eroded gabions, and scarp above, June 15, 2006.





Photo 4 - Looking southwest along channel from culvert outlet at slumping and erosion June 15, 2006.





Photo 5 - Looking east along highway. Note dips in highway overtop culvert, June 15, 2006.