



Photo 1 – General view of slope, facing west across slide area. Red casing protector on right of photo is the new SI installed in AMEC BH2 (February 2001) to replace sheared-off SI #7.



Photo 2 – Oversteepened slope immediately below concrete pile wall along downslope edge of road. Note dip in guardrail.



Photo 3 – May 2001 photo of toe of slide approximately 150 m below road.



Photo 4 – June 2000 photo of toe of slide approximately 150 m below road.