



Photo S4-1 – June 2008 (top)

Facing south along the original fenceline with the westwards slope crest retrogression towards Highway 2 visible. The temporary fenceline along the slope crest/landslide headscarp has been installed since the June 2007 inspection.



Photo S4-2 – June 2008 (bottom)

Closer view of the oversteepened headscarp west of the original fenceline.