



Photo S10(A)-1 – June 2008 (top)

Facing northbound across the south flank of the landslide damage to the highway. The circular crack delineating the settlement area in the southbound lane (left side of the photo) has formed repeatedly in recent years through numerous overlays and patches.



Photo S10(A)-2 – June 2008 (bottom)

Facing southbound across the landslide damage to the highway.



Photo S10(A)-3 – June 2008 (top)

Closer view, facing southbound, of the visible south flank of the landslide scarp that extends back to the centerline of the highway.