



Photo 1 – June 2009

Creek erosion site at KM 82.2, repaired with rip-rap. The site was not damaged by the Spring 2009 runoff, however there is potential for future erosion at, or near, the repaired area.



Photo 2 – June 2009

Creek erosion site at KM 82.4. Erosion does not appear to be occurring, however there is a risk that peak flow events may trigger erosion in the future that would affect the road.