



**Photo S38-1 - June 2011**  
Facing southbound across the cracks in the road surface. Note the settlement visible in the upper left corner of the photo near the guard rail.



**Photo S38-2 - July 2011**  
Photo taken from the same location as Photo S38-1, approximately one month later. The road has been paved within the last month, with cracks forming through the overlay.



**Photo S38-3 - June 2011**  
Facing southbound across the slide area.