



Photo S8-1 (upper left) – June 2005 – facing north across the northern area of the site. No significant cracking or settlement was noted.



Photo S8-2 (lower left) – June 2005 – facing south along the southern area of the site. No significant cracking or settlement was noted.



Photo S8-3 (lower right) – June 2005 – Pneumatic piezometer lead cables exposed in Borehole 2002-2. Protective cover has been destroyed, most likely by a snowplow.